


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Paulo de Tarso Operadora/Cliente: Ederson Martins Pires

GRE/Prodemge: João Antinossi Responsável/cliente: Antônio Marcos Lopes Ferreira

> Porta kbps Plataforma Consórcio **VSAT-ID** EMC/Vodanet 2Mbps **VSAT** SEE-SACO-22216



## Satellite (DVB) RX Configuration

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Enable Name

\* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

## Satellite (DVB) Receiver Status \_\_\_\_\_\_

Rx State : On

: Forward link up DVB State

Network : 65281, Prodemge@Vodanet Frequency : 12.176376 GHz Symbol Rate : 4.882995 Msps

S2 ModCod - receiving : 20 16APSK-4/5

- current max : 21 16APSK-5/6

Pilot : On
Frame length : Short
DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 : 17.5 dB : -35 dBm SNR Input Power

```
Satellite (DVB) TX Configuration
______
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
State : On (DVB-RCS2)
IDU Output Power : -16.6 dBm
ODU Output Power : 33.0 dBm
EIRP
                   : 46.3 dBW
Es/No
                    : 14.0 dB
Header Compression : Disabled - HC for RCS2 not supported by HUB
Timing correction
                    : -433 us (281686 us)
Frequency correction: 40 Hz
System Information:
                        : SEE-SACO-22216
    Name
    Location
                        : SÃO FRANCISCO
    Contact.
    System Up time : 0 days, 00:19:22
    CPU Load
                       : 19%
    System time(UTC) : 17 October 2017 12:14:19 Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                       : 120033
    Main board ID
                       : 120026 R6.1
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:48:ff
Satellite (DVB) : 00:20:0e:10:48:ff
# arp show
   NetAddr
                State MacAddr
                                              Τf
    10.213.15.2 Dynamic 1c:39:47:5b:e2:48 1
Pinging 10.213.15.1 with 32 bytes of data:
Reply from 10.213.15.1: bytes=32 time=555ms TTL=56
Reply from 10.213.15.1: bytes=32 time=588ms TTL=56
Reply from 10.213.15.1: bytes=32 time=567ms TTL=56
Reply from 10.213.15.1: bytes=32 time=575ms TTL=56
Reply from 10.213.15.1: bytes=32 time=565ms TTL=56
Reply from 10.213.15.1: bytes=32 time=591ms TTL=56
Reply from 10.213.15.1: bytes=32 time=544ms TTL=56
Reply from 10.213.15.1: bytes=32 time=571ms \mathtt{TTL}=56
Reply from 10.213.15.1: bytes=32 time=555ms TTL=56
Reply from 10.213.15.1: bytes=32 time=563ms TTL=56
Ping statistics for 10.213.15.1:
   Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
   Minimum = 544ms, Maximum = 591ms, Average = 567ms
```

Lista de sites acessados:
www.globo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok
Responsável pelo teste de navegação: Nome: Antônio Marcos Lopes ferreira Função: Diretor Identidade: M-5904670 Telefone: (38) 3631-2212 Horário de funcionamento da escola: 07:00 as 18:00