

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Hernan Alves Operadora/Cliente: Eduardo Tadra

Responsável/cliente: Edna Neves Paulino GRE/Prodemge: João Antinossi

> Consórcio **VSAT-ID** Porta kbps **Plataforma** EMC/Vodanet SEE-IPGA-22596 2Mbps **VSAT**

Port eth0 on SEE-IPGA-22596 (10.214.187.1)



Satellite (DVB) RX Configuration -----Auto start : Enabled

Auto start

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 0 0.0 E 16.667000 11.962753 DVB-S2 2

Yes

Satellite (DVB) Receiver Status _____

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176348 GHz

Symbol Rate : 4.883032 Msps DVB State
Network
Frequency

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short
DVB S2 Mode : ACM
DVB S2 Stroom DVB S2 Stream type : MPEG-TS

```
: 0.20
Roll off
SNR
                     : 16.7 dB
Input Power
                    : -29 dBm
# dvb tx show
Satellite (DVB) TX Configuration
_____
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm EIRP : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
______
State : On (DVB-RCS2)
IDU Output Power : -20.7 dBm
ODU Output Power : 33.4 dBm
EIRP
EIRP
                     : 46.7 dBW
Es/No : 14.0 dB
Header Compression : Disabled - HC for RCS2 not supported by HUB
Timing correction : -357 us (281497 us)
Frequency correction: 80 Hz
# device snow
System Information:
    Name : SEE-IPGA-22596
    Togation : IPATINGA - MG
# device show
    System Up time : 0 days, 00:34:59
CPU Load : 17%
System time(UTC) : 07 November 2017 14:34:21
Broadcast Message : not set
HW:
   Model
                         : SatLink 2000
    HW ID
                         : 120033
   Main board ID
                       : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:58:40
Satellite (DVB) : 00:20:0e:10:58:40
# arp show
              State MacAddr
   10.214.187.2 Dynamic b8:70:f4:6e:b3:ab 1
#
Pinging 10.214.187.1 with 32 bytes of data:
Reply from 10.214.187.1: bytes=32 time=526ms TTL=56
Reply from 10.214.187.1: bytes=32 time=523ms TTL=56
Reply from 10.214.187.1: bytes=32 time=529ms TTL=56
Reply from 10.214.187.1: bytes=32 time=613ms TTL=56
Reply from 10.214.187.1: bytes=32 time=562ms TTL=56
Reply from 10.214.187.1: bytes=32 time=544ms TTL=56
Reply from 10.214.187.1: bytes=32 time=635ms TTL=56
Reply from 10.214.187.1: bytes=32 time=539ms TTL=56
Reply from 10.214.187.1: bytes=32 time=517ms TTL=56
Reply from 10.214.187.1: bytes=32 time=543ms TTL=56
```

```
Ping statistics for 10.214.187.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 517ms, Maximum = 635ms, Average = 553ms
```

Lista de sites acessados:

www.globo.com - ok www.yahoo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok

Responsável pelo teste de navegação:

Nome: Edna Neves Paulino

Função: Diretora MASP: 969082-7

Telefone: (31) 38232510

Funcionamento: 07:00 às 18:00h