


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Ederson Martins

GRE/Prodemge: João Antinossi Responsável/cliente: Diego Armando de Souza

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-SACO-222302MbpsVSAT



PRTG Traffic Grapher V6.2.0.907 - 19/10/2017 17:46:53

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176142 GHz Symbol Rate : 4.882995 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short
DVB S2 Mode : ACM
DVB S2 Stream type : MPEG-TS
Roll off : 0.20
SNR : 16.3 dB
Input Power : -39 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -21 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -15.2 dBm
ODU Output Power : 32.7 dBm
EIRP
                     : 46.0 dBW
Es/No
                     : 14.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -337 us (281690 us)
Frequency correction: 110 Hz
System Information:
                    : SEE-SACO-22230
    Name
    Location
                         : SÃO FRANCISCO - MG
    Contact
    System Up time : 0 days, 00:02:28

CPU Load : 11%

System time(UTC) : 19 October 2017 16:52:34
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:4a:e4
Satellite (DVB) : 00:20:0e:10:4a:e4
NetAddr
           State MacAddr
    10.213.29.2 Dynamic 1c:39:47:5b:e2:48 1
Pinging 10.213.29.1 with 32 bytes of data:
Reply from 10.213.29.1: bytes=32 time=545ms TTL=56
Reply from 10.213.29.1: bytes=32 time=579ms TTL=56
Reply from 10.213.29.1: bytes=32 time=587ms TTL=56
Reply from 10.213.29.1: bytes=32 time=590ms TTL=56
Reply from 10.213.29.1: bytes=32 time=576ms TTL=56
Reply from 10.213.29.1: bytes=32 time=570ms TTL=56
Reply from 10.213.29.1: bytes=32 time=585ms TTL=56
Reply from 10.213.29.1: bytes=32 time=601ms TTL=56
Reply from 10.213.29.1: bytes=32 time=576ms TTL=56
Reply from 10.213.29.1: bytes=32 time=583ms TTL=56
Ping statistics for 10.213.29.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 545ms, Maximum = 601ms, Average = 579ms
```

Lista de sites acessados:
www.globo.com – ok
<u>www.hotmail.com</u> – ok
<u>www.google.com</u> – ok
<u>www.educacao.mg.gov.br</u> – ok
<u>www.prodemge.gov.br</u> – ok
Responsável pelo teste de navegação: Nome: Diego Armando de Souza Função: Assistente Técnico de Educação Básica Identidade: MG 16.734.582
Telefone: 38-99945-8544
Horário de funcionamento – 07hrs às 17:30hrs
<u>L</u>