


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Jean Polini

GRE/Prodemge: João Antinossi Responsável/cliente: Itamar Souza Ferreira Krenak

> Consórcio Porta kbps Plataforma **VSAT-ID** EMC/Vodanet SEE-REOR-23204 **VSAT** 2Mbps



Satellite (DVB) RX Configuration _____

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

8.883000 12.176420 DVB-S2 104 0 0.0 E * 0 0

Satellite (DVB) Receiver Status

: On Rx State

: Forward link up DVB State

: 65281, Prodemge@Vodanet Network

: 03201, -: 12.176459 GHz : 8.882910 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 22 16APSK-8/9 - current max : 22 16APSK-8/9

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.4 dB Input Power : -38 dBm

```
Satellite (DVB) TX Configuration
_____
                    : Enabled
Auto start
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
: On (DVB-RCS2)

IDU Output Power : -20.0 dBm

Es/No
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -327 us (265759 us)
Frequency correction: 130 Hz
System Information:
   Name
                        : SEE-REOR-23204
    Location
                         : RESPLENDOR - MG
    Contact
    System Up time : 0 days, 00:04:18 CPU Load : 35%
    System time(UTC) : 12 December 2017 13:25:23
Broadcast Message : not set
    System time(UTC)
HW:
    Model
                        : SatLink 2000
                        : 120033
    HW ID
                        : 120026 R6.2
    Main board ID
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:5c:c2
Satellite (DVB) : 00:20:0e:10:5c:c2
NetAddr
          State MacAddr
   10.214.239.2 Dynamic 64:1c:67:62:2e:12 1
Pinging 10.214.239.1 with 32 bytes of data:
Reply from 10.214.239.1: bytes=32 time=549ms TTL=56
Reply from 10.214.239.1: bytes=32 time=549ms TTL=56
Reply from 10.214.239.1: bytes=32 time=584ms TTL=56
Reply from 10.214.239.1: bytes=32 time=587ms TTL=56
Reply from 10.214.239.1: bytes=32 time=584ms TTL=56
Reply from 10.214.239.1: bytes=32 time=530ms TTL=56
Reply from 10.214.239.1: bytes=32 time=520ms TTL=56
Reply from 10.214.239.1: bytes=32 time=710ms TTL=56
Reply from 10.214.239.1: bytes=32 time=544ms TTL=56
Reply from 10.214.239.1: bytes=32 time=545ms TTL=56
Ping statistics for 10.214.239.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 520ms, Maximum = 710ms, Average = 570ms
```

Lista de sites acessados: <u>www.globo.com</u> – ok www.yahoo.com - ok <u>www.hotmail.com</u> – ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: Itamar Souza Ferreira Krenak Função: Diretor MASP: 843673-4 Telefone: 33-999700295 Funcionamento: 08:00h às 14:30h