


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Jean Polini

**GRE/Prodemge:** João Antinossi Responsável/cliente: Itamar Souza Ferreira Krenak

> Porta kbps Plataforma Consórcio **VSAT-ID VSAT** EMC/Vodanet SEE-REOR-23203 2Mbps



## Satellite (DVB) RX Configuration \_\_\_\_\_

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

\* 0 0 8.883000 12.176420 DVB-S2 104 0 0.0 E

Yes

4.883300 12.176420 DVB-S2 104 0 0.0 E 1 1

Yes

## Satellite (DVB) Receiver Status \_\_\_\_\_\_

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

: 65281, 110 : 12.176434 GHz : 8.882953 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 22 16APSK-8/9

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.2 dB Input Power : -40 dBm

```
Satellite (DVB) TX Configuration
_____
                    : Enabled
Auto start
Auto start : Enabled IDU Output Power : -18 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
: On (DVB-RCS2)

IDU Output Power : -17.8 dBm

Es/No
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -248 us (265767 us)
Frequency correction: 140 Hz
System Information:
   Name
                        : SEE-REOR-23203
    Location
                         : Resplendor - MG
    Contact
    System Up time : 0 days, 00:01:57 CPU Load : 27%
    System time(UTC) : 12 December 2017 17:51:01
Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
                        : 120033
    HW ID
                        : 120026 R6.2
    Main board ID
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:4f:4d
Satellite (DVB) : 00:20:0e:10:4f:4d
NetAddr
             State MacAddr
   10.214.238.2 Dynamic 64:1c:67:62:2e:12 1
Pinging 10.214.238.1 with 32 bytes of data:
Reply from 10.214.238.1: bytes=32 time=587ms TTL=56
Reply from 10.214.238.1: bytes=32 time=528ms TTL=56
Reply from 10.214.238.1: bytes=32 time=579ms TTL=56
Reply from 10.214.238.1: bytes=32 time=538ms TTL=56
Reply from 10.214.238.1: bytes=32 time=531ms TTL=56
Reply from 10.214.238.1: bytes=32 time=661ms TTL=56
Reply from 10.214.238.1: bytes=32 time=522ms TTL=56
Reply from 10.214.238.1: bytes=32 time=624ms TTL=56
Reply from 10.214.238.1: bytes=32 time=570ms TTL=56
Reply from 10.214.238.1: bytes=32 time=585ms TTL=56
Ping statistics for 10.214.238.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 522ms, Maximum = 661ms, Average = 572ms
```

## Lista de sites acessados: <u>www.globo.com</u> – ok www.yahoo.com - ok <u>www.hotmail.com</u> – ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: Itamar Souza Ferreira Krenak Função: Diretor MASP: 843673-4 Telefone: 33999700295 Funcionamento: 07:00h às 20:30h