

TERMO DE ACEITE TÉCNICO

Name

Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior

GRE/Prodemge: João Antinossi


Consórcio
EMC/Vodanet

Porta kbps
SEE-INRA-22777

SEE-INRA-22777

SEE-INRA-22777





SatLink 2000

- Main board ID 120026, Revision R6.2
- SW ID 120208, Revision 16.0.1 Build 57

dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E Yes 1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176674 GHz Symbol Rate : 4.883026 Msps

S2 ModCod

- receiving : 20 16APSK-4/5 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short
DVB S2 Mode : ACM
DVB S2 Stream type : MPEG-TS

 $Roll \ off \qquad : 0.20$

```
SNR
             : 15.6 dB
Input Power
               : -36 dBm
# dvb tx show
Satellite (DVB) TX Configuration
Auto start
             : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
             : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode
               : VC-Mux
Header Compression: UDP/IP
Satellite (DVB) Transmitter Status
            : On (DVB-RCS2)
State
IDU Output Power : -20.6 dBm
ODU Output Power : 33.3 dBm
EIRP
             : 46.6 dBW
Es/No
             : 13.5 dB
Header Compression: Disabled - HC for RCS2 not supported by HUB
Timing correction : -452 us (281581 us)
Frequency correction: 40 Hz
# arp show
             State MacAddr
 NetAddr
  10.214.85.2 Dynamic b4:99:ba:00:92:6b 1
## device show
System Information:
                : SEE-INRA-22777
  Name
  Location
                : Indaiabira - MG
  Contact
  System Up time
                   : 0 days, 00:14:04
                  : 26%
  CPU Load
  System time(UTC) : 14 November 2017 18:51:30
  Broadcast Message : not set
HW:
  Model
                : SatLink 2000
  HW ID
                 : 120033
  Main board ID
                   : 120026 R6.2
MAC addresses:
  Ethernet (LAN)
                   : 00:20:0e:10:4c:3b
  Satellite (DVB)
                  : 00:20:0e:10:4c:3b
Pinging 10.214.85.1 with 32 bytes of data:
Reply from 10.214.85.1: bytes=32 time=610ms TTL=56
Reply from 10.214.85.1: bytes=32 time=524ms TTL=56
Reply from 10.214.85.1: bytes=32 time=550ms TTL=56
Reply from 10.214.85.1: bytes=32 time=548ms TTL=56
Reply from 10.214.85.1: bytes=32 time=575ms TTL=56
Reply from 10.214.85.1: bytes=32 time=558ms TTL=56
Reply from 10.214.85.1: bytes=32 time=554ms TTL=56
Reply from 10.214.85.1: bytes=32 time=629ms TTL=56
```

Reply from 10.214.85.1: bytes=32 time=538ms TTL=56 Reply from 10.214.85.1: bytes=32 time=532ms TTL=56

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),

Minimum = 524ms, Maximum = 629ms, Average = 561ms

Approximate round trip times in milli-seconds:

Ping statistics for 10.214.85.1:

www.yahoo.com.br

www.hotmail.com

www.google.com

www.prodemge.gov.br

Responsável	Ilda Mendes de Oliveira
Cargo	Vice - diretora
Identidade	930830-0
Telefone	***
Funcionamento	07:00-22:20
Onde ficou	Secretaria da escola