


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Rodrigo Alves

GRE/Prodemge: João Antinossi Responsável/cliente: Ivanilde Jose de Oliveira

> Porta kbps Plataforma Consórcio **VSAT-ID** EMC/Vodanet SEE-BRAS-23225 2Mbps **VSAT**



Satellite (DVB) RX Configuration

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 12.176420 DVB-S2 104 0 0.0 E 4.883300

Yes

16.667000 11.962753 DVB-S2 2 0 0.0 E 1 1

Yes

Satellite (DVB) Receiver Status ______

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

: 65281, Proder : 12.176584 GHz Frequency Symbol Rate : 4.883029 Msps

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.9 dB Input Power : -30 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -15.3 dBm
ODU Output Power : 33.0 dBm
EIRP
                    : 46.3 dBW
Es/No
                    : 13.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -269 us (281544 us)
Frequency correction: 130 Hz
System Information:
    Name
                       : SEE-BRAS-23225
    Location
                        : Brasília de Minas /MG
    Contact
    System Up time : 0 days, 00:15:36 CPU Load : 15%
    System time(UTC) : 29 November 2017 19:26:56
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                       : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:57:fa
Satellite (DVB) : 00:20:0e:10:57:fa
    Ethernet (LAN)
NetAddr
          State MacAddr
   10.213.167.2 Dynamic 2c:27:d7:a0:cd:ed 1
Pinging 10.213.167.1 with 32 bytes of data:
Reply from 10.213.167.1: bytes=32 time=525ms TTL=56
Reply from 10.213.167.1: bytes=32 time=530ms TTL=56
Reply from 10.213.167.1: bytes=32 time=544ms TTL=56
Reply from 10.213.167.1: bytes=32 time=519ms TTL=56
Reply from 10.213.167.1: bytes=32 time=523ms TTL=56
Reply from 10.213.167.1: bytes=32 time=572ms TTL=56
Reply from 10.213.167.1: bytes=32 time=546ms TTL=56
Reply from 10.213.167.1: bytes=32 time=537ms TTL=56
Reply from 10.213.167.1: bytes=32 time=619ms TTL=56
Reply from 10.213.167.1: bytes=32 time=565ms TTL=56
Ping statistics for 10.213.167.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 519ms, Maximum = 619ms, Average = 548ms
```

Lista de sites acessados:
<u>www.globo.com</u> – ok <u>www.yahoo.com</u> – ok
www.hotmail.com – ok
www.google.com – ok
www.educacao.mg.gov.br – ok www.prodemge.gov.br – ok
<u>www.proderiige.gov.br</u> – 0k
Responsável pelo teste de navegação:
Nome: Ivanilde Jose de Oliveira
Função: Diretora
MASP: 3685245
Telefone: 38-32311590
Telefolic. 36-32311370
Funcionamento: 07:00h às 22:30h