

TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE


NOC/Operadora: Paulo de Tarso Operadora/Cliente: Gustavo de Oliveira da Silva

GRE/Prodemge: João Antinossi

Responsável/cliente: Jose da Silva Marques da

Cunha

Consórcio VSAT-ID Plataforma Porta kbps EMC/Vodanet SEE-SAAS-22958 2048/1024 **VSAT**



Satellite (DVB) RX Configuration _____

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 0 0.0 E * 0 0

Yes

Satellite (DVB) Receiver Status

: On Rx State

: Forward link up DVB State

Network : 65281, Prodemge@Vodanet

Frequency : 12.176506 GHz Symbol Rate : 4.882908 Msps Frequency

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On Frame length : Shown DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.3 dB Input Power : -31 dBm

```
Satellite (DVB) TX Configuration
 _____
Auto start
                     : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                     : 46.5 dBW
Default CW Frequency: 0.000000 GHz
                      : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
                     : On (DVB-RCS2)
State
IDU Output Power : -17.3 dBm
ODU Output Power : 33.3 dBm
EIRP
                      : 46.6 dBW
Es/No
                      : 14.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{: Disabled} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -299 us (280181 us)
Frequency correction: -30 Hz
System Information:
                      : SEE-SAAS-22958
   Name
    Location
                      : Santa Helena de Minas - MG
    Contact
    System Up time : 0 days, 09:38:59
   CPU Load : 15%
System time(UTC) : 23 November 2017 10:23:28
Broadcast Message : not set
HW:
                      : SatLink 2000
    Model
                       : 120033
    HW ID
                       : 120026 R6.2
   Main board ID
MAC addresses:
                   : 00:20:0e:10:69:02
: 00:20:0e:10:69:02
    Ethernet (LAN)
    Satellite (DVB)
# arp show
               State MacAddr
   NetAddr
   10.215.157.2 Dynamic 64:1c:67:61:83:29 1
Pinging 10.215.157.1 with 32 bytes of data:
Reply from 10.215.157.1: bytes=32 time=560ms TTL=56
Reply from 10.215.157.1: bytes=32 time=552ms TTL=56
Reply from 10.215.157.1: bytes=32 time=548ms TTL=56
Reply from 10.215.157.1: bytes=32 time=521ms TTL=56
Reply from 10.215.157.1: bytes=32 time=815ms TTL=56
Reply from 10.215.157.1: bytes=32 time=544ms TTL=56
Reply from 10.215.157.1: bytes=32 time=567ms TTL=56
Reply from 10.215.157.1: bytes=32 time=551ms TTL=56
Reply from 10.215.157.1: bytes=32 time=527ms TTL=56
Reply from 10.215.157.1: bytes=32 time=626ms TTL=56
Ping statistics for 10.215.157.1:
   Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 521ms, Maximum = 815ms, Average = 581ms
```

| Lista de sites acessados: |
|---|
| |
| <u>www.globo.com</u> – ok |
| <u>www.hotmail.com</u> – ok |
| <u>www.google.com</u> – ok |
| <u>www.educacao.mg.gov.br</u> – ok |
| Responsável pelo teste de navegação: Nome: Jose da Silva Marques da Cunha Função: Coordenador MASP 639640-2 Telefone: (31) 9 8870-8914 Horário de funcionamento da escola: 07:00 as 16:45 |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |