

# TERMO DE ACEITE TÉCNICO

Name

Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior

GRE/Prodemge: João Antinossi

Consórcio
EMC/Vodanet


Paula Pereira

VSAT-ID
SEE-BOAS-22102

Porta kbps
2Mbps

Plataforma
VSAT





## SatLink 2000

- Main board ID 120026, Revision R6.2

- SW ID 120208, Revision 16.0.1 Build 57

# dvb rx show

## Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Enable

\* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E Yes 1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E Yes

## Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176674 GHz Symbol Rate : 4.883026 Msps

S2 ModCod

- receiving : 20 16APSK-4/5 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short
DVB S2 Mode : ACM
DVB S2 Stream type : MPEG-TS

Roll off : 0.20 SNR : 15.6 dB Input Power : -36 dBm

# dvb tx show

## Satellite (DVB) TX Configuration

Auto start : Enabled IDU Output Power : -20 dBm IDU Max Output Power: 0.0 dBm ODU Output Power : 33.2 dBm

EIRP : 46.5 dBW

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

## Satellite (DVB) Transmitter Status

\_\_\_\_\_

State : On (DVB-RCS2)
IDU Output Power : -20.6 dBm
ODU Output Power : 33.3 dBm
EIRP : 46.6 dBW
Es/No : 13.5 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction: -452 us (281581 us)

Frequency correction: 40 Hz

### # arp show

NetAddr State MacAddr If 10.212.155.1 Dynamic 00200E104C46 1

#### # device show

**System Information:** 

Name : SEE-BOAS-22102

Location : BONITO DE MINAS - MG

Contact

System Up time : 0 days, 23:34:01

CPU Load : 15%

System time(UTC) : 13 November 2017 12:47:29

Broadcast Message : not set

#### HW:

Model : SatLink 2000 HW ID : 120033 Main board ID : 120026 R6.2

#### MAC addresses:

Ethernet (LAN) : 00:20:0e:10:4c:46 Satellite (DVB) : 00:20:0e:10:4c:46

## Pinging 10.212.155.1 with 32 bytes of data:

Reply from 10.212.155.1: bytes=32 time=520ms TTL=56 Reply from 10.212.155.1: bytes=32 time=548ms TTL=56 Reply from 10.212.155.1: bytes=32 time=574ms TTL=56 Reply from 10.212.155.1: bytes=32 time=557ms TTL=56 Reply from 10.212.155.1: bytes=32 time=530ms TTL=56 Reply from 10.212.155.1: bytes=32 time=542ms TTL=56 Reply from 10.212.155.1: bytes=32 time=542ms TTL=56 Reply from 10.212.155.1: bytes=32 time=548ms TTL=56 Reply from 10.212.155.1: bytes=32 time=545ms TTL=56 Reply from 10.212.155.1: bytes=32 time=545ms TTL=56 Reply from 10.212.155.1: bytes=32 time=527ms TTL=56

Ping statistics for 10.212.155.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),

Approximate round trip times in milli-seconds:

Minimum = 520ms, Maximum = 574ms, Average = 554ms

www.yahoo.com.br

### www.hotmail.com

## www.google.com

# www.prodemge.gov.br

| Responsável   | Paula Pereira   |
|---------------|-----------------|
| Cargo         | Diretora        |
| Identidade    | 1313102-4       |
| Telefone      | 038-9-9808-6920 |
| Funcionamento | 07:00-18:00     |