

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: João Gustavo

GRE/Prodemge: João Antinossi Responsável/cliente: Claudiana Oliveira Souza

> Consórcio Porta kbps Plataforma **VSAT-ID** EMC/Vodanet **VSAT** SEE-DIIS-23120 2Mbps

Port eth0 on SEE-DIIS-23120 (10.214.32.1)



Satellite (DVB) RX Configuration _____

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

12.176420 DVB-S2 104 0 0.0 E * 0 0 4.883300

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State

Network

: Forward link up : 65281, Prodemge@Vodanet : 12.176762 GHz : 4.882995 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

: On Pilot Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS : 0.20 Roll off : 16.0 dB SNR Input Power : -29 dBm

```
Satellite (DVB) TX Configuration
_____
Auto start
                    : Enabled
Auto start : Enabled IDU Output Power : -30 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : max
EIRP
                     : max
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -18.0 dBm
ODU Output Power : 35.0 dBm
EIRP
                     : 48.3 dBW
Es/No
                     : 14.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -174 us (280048 us)
Frequency correction: 110 Hz
System Information:
                    : SEE-DIIS-23120
    Name
    Location
                         : DIVIS | POLIS / MG
    Contact
    System Up time : 0 days, 00:34:26
CPU Load : 14%
System time(UTC) : 02 December 2017 19:22:52
    Broadcast Message : not set
HW:
    Model
                         : SatLink 2000
    HW ID
                         : 120033
    Main board ID
                        : 120026 R6.2
    control (LAN) : 00:20:0e:10:4c:9b
Satellite (DVB) : 00:20:0e:10:4c:9b
MAC addresses:
NetAddr
           State MacAddr
    10.214.32.2 Dynamic b4:99:ba:00:92:6b 1
Pinging 10.214.32.1 with 32 bytes of data:
Reply from 10.214.32.1: bytes=32 time=576ms TTL=56
Reply from 10.214.32.1: bytes=32 time=565ms TTL=56
Reply from 10.214.32.1: bytes=32 time=557ms TTL=56
Reply from 10.214.32.1: bytes=32 time=569ms TTL=56
Reply from 10.214.32.1: bytes=32 time=575ms TTL=56
Reply from 10.214.32.1: bytes=32 time=526ms TTL=56
Reply from 10.214.32.1: bytes=32 time=527ms TTL=56
Reply from 10.214.32.1: bytes=32 time=549ms TTL=56
Reply from 10.214.32.1: bytes=32 time=522ms TTL=56
Reply from 10.214.32.1: bytes=32 time=523ms TTL=56
Ping statistics for 10.214.32.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 522ms, Maximum = 576ms, Average = 548ms
```

Lista de sites acessados: <u>www.globo.com</u> – ok www.yahoo.com - ok <u>www.hotmail.com</u> – ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: Claudiana Oliveira Souza Função: Diretora MASP: 1096465-8 Telefone: 33-988414373 Funcionamento: 07:00h às 18:00h