


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Paulo de Tarso Operadora/Cliente: João Gustavo F M Sobrinho

Responsável/cliente: Sidney Miguel da silva GRE/Prodemge: João Antinossi

> Consórcio VSAT-ID Porta kbps Plataforma EMC/Vodanet SEE-MOUL-22535 2048/1024 **VSAT**



Satellite (DVB) RX Configuration _____

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 0 0.0 E * 0 0

Yes

Satellite (DVB) Receiver Status

: On Rx State

: Forward link up DVB State

: 65281, Prodemge@Vodanet Network

Frequency : 12.176321 GHz
Symbol Rate : 4.882956 Msps

S2 ModCod

- receiving : 19 16APSK-3/4 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.6 dB Input Power : -32 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
                    : 46.5 dBW
EIRP
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
: On (DVB-RCS2)

IDU Output Power : -14.5 dBm

ODU Output Power : 35.2 dBm

EIRP
______
Es/No
                     : 15.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -321 us (280778 us)
Frequency correction: 120 Hz
# device show
System Information:
    Name
                         : SEE-MOUL-22535
    Location
                         : Monte Azul - MG
    Contact
                        :
    System Up time : 0 days, 01:08:38
CPU Load : 7%
System time(UTC) : 05 November 2017 17:03:12
    Broadcast Message : not set
HW:
    Model
                         : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:5b:cf
Satellite (DVB) : 00:20:0e:10:5b:cf
Pinging 10.213.118.1 with 32 bytes of data:
Reply from 10.213.118.1: bytes=32 time=573ms TTL=56
Reply from 10.213.118.1: bytes=32 time=591ms TTL=56
Reply from 10.213.118.1: bytes=32 time=585ms TTL=56
Reply from 10.213.118.1: bytes=32 time=556ms TTL=56
Reply from 10.213.118.1: bytes=32 time=588ms TTL=56
Reply from 10.213.118.1: bytes=32 time=549ms TTL=56
Reply from 10.213.118.1: bytes=32 time=568ms TTL=56
Reply from 10.213.118.1: bytes=32 time=584ms TTL=56
Reply from 10.213.118.1: bytes=32 time=607ms TTL=56
Reply from 10.213.118.1: bytes=32 time=542ms TTL=56
Ping statistics for 10.213.118.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 542ms, Maximum = 607ms, Average = 574ms
           State MacAddr
  NetAddr
   10.213.118.2 Dynamic b4:99:ba:00:92:6b 1
```

Lista de sites acessados: <u>www.globo.com</u> – ok www.yahoo.com - ok <u>www.hotmail.com</u> – ok www.google.com – ok <u>www.educacao.mg.gov.br</u> – ok www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: Sidney Miguel da silva Função: Diretor Telefone: 3899802-8235 MASP 974744-5 Horário de Funcionamento: 07:00 AS 17:20