


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Ricardo Benavides Operadora/Cliente: Jean Polini

GRE/Prodemge: João Antinossi Responsável/cliente: Cleide Lucia Gonzaga Lopes

> Porta kbps Plataforma Consórcio **VSAT-ID** EMC/Vodanet **VSAT** SEE-MACU-23679 2Mbps



Satellite (DVB) RX Configuration \_\_\_\_\_\_ Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

\* 0 0 8.883000 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 4.883300 12.176420 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

: Forward link up DVB State

: 65281, Prodemge@Vodanet Network

: 12.176497 GHz : 8.883065 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 22 16APSK-8/9 - current max : 22 16APSK-8/9

Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.7 dB Input Power : -43 dBm

```
Satellite (DVB) TX Configuration
_____
Auto start : Enabled IDU Output Power : -18 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
                   : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -18.2 dBm
Es/No : 14.5 dB
Header Compression : Disabled - HC for RCS2 not supported by HUB
Timing correction : -242 us (266303 us)
Frequency correction: 160 Hz
System Information:
   Name
                        : SEE-MACU-23679
    Location
                        : Manhua¦u - MG
    Contact
    System Up time : 0 days, 00:29:26 CPU Load : 21%
    System time(UTC) : 16 January 2018 18:31:53
Broadcast Message : not set
HW:
   Model
                        : SatLink 2000
                       : 120033
    HW ID
                       : 120026 R6.2
    Main board ID
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:7b:41
    Satellite (DVB)
                       : 00:20:0e:10:7b:41
NetAddr
             State
                      MacAddr
10.215.38.2 Dynamic 64:1c:67:62:2e:12 1
Pinging 10.148.3.98 with 32 bytes of data:
Reply from 10.148.3.98: bytes=32 time=525ms TTL=62
Reply from 10.148.3.98: bytes=32 time=524ms TTL=62
Reply from 10.148.3.98: bytes=32 time=571ms TTL=62
Reply from 10.148.3.98: bytes=32 time=636ms TTL=62
Reply from 10.148.3.98: bytes=32 time=512ms TTL=62
Reply from 10.148.3.98: bytes=32 time=541ms TTL=62
Reply from 10.148.3.98: bytes=32 time=538ms TTL=62
Reply from 10.148.3.98: bytes=32 time=531ms TTL=62
Reply from 10.148.3.98: bytes=32 time=555ms TTL=62
Reply from 10.148.3.98: bytes=32 time=533ms TTL=62
Ping statistics for 10.148.3.98:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 512ms, Maximum = 636ms, Average = 546ms
```

Lista de sites acessados:
<u>www.globo.com</u> – ok
www.yahoo.com - ok
<u>www.hotmail.com</u> – ok
<u>www.google.com</u> – ok
<u>www.educacao.mg.gov.br</u> – ok
<u>www.prodemge.gov.br</u> – ok
Responsável: Cleide Lucia Gonzaga Lopes
Cargo: ATM Auxiliar de Secretaria
MASP: 599 020-5
Telefone: 33 3331-2158
Horário de funcionamento: 07:00 as 18:00
Horario de funcionamento. 07.00 as 16.00