


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Guilherme Cunha Operadora/Cliente: Ederson Martins

Responsável/cliente: Soraya Jamel GRE/Prodemge: João Antinossi

> Consórcio Porta kbps Plataforma **VSAT-ID** 2048/1024 EMC/Vodanet SEE-BRAS-23228 VSAT



PRTG Traffic Grapher V6.2.0.907 - 29/11/2017 22:19:28

dvb rx show

Satellite (DVB) RX Configuration -----

Auto start . Enable:
Max Traffic MODCOD : 23 16APSK-9/10
PY watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

: On Rx State

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

: 12.176644 GHz Frequency Symbol Rate : 4.883018 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short DVB S2 Mode : ACM

```
DVB S2 Stream type : MPEG-TS
Roll off : 0.20
SNR
                  : 15.7 dB
Input Power
                   : -33 dBm
# dvb tx show
Satellite (DVB) TX Configuration
-----
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                   : 46.5 dBW
Default CW Frequency: 0.000000 GHz
                   : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
State : On (DVB-RCS2)
IDU Output Power : -19.1 dBm
ODU Output Power : 33.1 dBm
EIRP
                   : 46.4 dBW
Es/No
                   : 11.5 dB
Header Compression : Disabled - HC for RCS2 not supported by HUB
Timing correction : -228 us (281525 us)
Frequency correction: 80 Hz
# device show
System Information:
                      : SEE-BRAS-23228
   Name
                      : Bras lia de Minas /MG
   Location
   Contact
   System Up time : 0 days, 00:33:37 CPU Load : 11%
   System time(UTC) : 29 November 2017 21:20:03
   Broadcast Message : not set
HW:
   Model
                       : SatLink 2000
    HW ID
                      : 120033
    Main board ID
                      : 120026 R6.1
   MAC addresses:
   Ethernet (LAN)
 Transec not Supported by this device !
# arp show
               State MacAddr
   NetAddr
   10.213.170.2 Dynamic 74:e6:e2:d4:e4:73 1
C:\Documents and Settings\Administrator.DVB-RCS.000>ping -n 15 10.213.170.1
Pinging 10.213.170.1 with 32 bytes of data:
Reply from 10.213.170.1: bytes=32 time=556ms TTL=56
Reply from 10.213.170.1: bytes=32 time=603ms TTL=56
Reply from 10.213.170.1: bytes=32 time=675ms TTL=56
Reply from 10.213.170.1: bytes=32 time=582ms TTL=56
Reply from 10.213.170.1: bytes=32 time=555ms TTL=56
Reply from 10.213.170.1: bytes=32 time=544ms TTL=56
```

```
Reply from 10.213.170.1: bytes=32 time=595ms TTL=56
Reply from 10.213.170.1: bytes=32 time=684ms TTL=56
Reply from 10.213.170.1: bytes=32 time=547ms TTL=56
Reply from 10.213.170.1: bytes=32 time=561ms TTL=56
Reply from 10.213.170.1: bytes=32 time=563ms TTL=56
Reply from 10.213.170.1: bytes=32 time=579ms TTL=56
Reply from 10.213.170.1: bytes=32 time=579ms TTL=56
Reply from 10.213.170.1: bytes=32 time=608ms TTL=56
Reply from 10.213.170.1: bytes=32 time=608ms TTL=56
Reply from 10.213.170.1: bytes=32 time=566ms TTL=56
Reply from 10.213.170.1: bytes=32 time=566ms TTL=56

Ping statistics for 10.213.170.1:

Packets: Sent = 15, Received = 15, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:

Minimum = 544ms, Maximum = 684ms, Average = 584ms
```

Lista de sites acessados:

www.globo.com_ok www.yahoo.com_ok www.hotmail.com_ok www.google.com_ok www.educacao.mg.gov.br_ok www.prodemge.gov.br_ok

Nome do responsável:alex tadeu mendes

Telefone:38-998685682

cargo: diretor

Identidade.Masp: 10845451

Seu nome e sobrenome: Sergio Almeida

seu Telefone:38-991261393