

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Hernan Alves Operadora/Cliente: João Gustavo F M Sobrinho

GRE/Prodemge: João Antinossi Responsável/cliente: Wagner da Silva Barros

> Consórcio **VSAT-ID** Porta kbps EMC/Vodanet **VSAT** SEE-MONT-22189 2Mbps





PRTG Traffic Grapher V6.2.0.907 - 1/11/2017 00:45:35

Satellite (DVB) RX Configuration

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog

: 15 minute RX watchdog

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

0.00000 0.000000 DVB-S2 2 0 0.0 E 1 1

Yes

Satellite (DVB) Receiver Status

Rx State : On

: Forward link up DVB State

Network : 65281, Prodemge@Vodanet

Frequency : 12.176139 GHz Symbol Rate : 4.883040 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 14.6 dB

```
Input Power
                  : -36 dBm
# dvb tx show
Satellite (DVB) TX Configuration
_____
                    : Enabled
Auto start
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : max
                    : max
EIRP
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -16.2 dBm
ODU Output Power : 34.5 dBm
EIRP
EIRP
                     : 47.8 dBW
                     : 13.5 dB
Es/No
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -202 us (281263 us)
Frequency correction: 50 Hz
# device show
System Information:

Name : SEE-MONT-22189

Location : Montalvania /MC
                         : Montalvania /MG
    System Up time : 0 days, 00:39:35 CPU Load : 9%
    System time(UTC) : 31 October 2017 23:35:50 Broadcast Message : not set
HW:
    Model
                         : SatLink 2000
                         : 120033
    HW ID
    Main board ID
                        : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:5c:0c
Satellite (DVB) : 00:20:0e:10:5c:0c
# arp show
                 State MacAddr
   10.212.242.2 Dynamic b4:99:ba:00:92:6b 1
#
C:\Documents and Settings\Administrator.DVB-RCS.000>ping -t 10.212.242.1
Pinging 10.212.242.1 with 32 bytes of data:
Reply from 10.212.242.1: bytes=32 time=557ms TTL=56
Reply from 10.212.242.1: bytes=32 time=553ms TTL=56
Reply from 10.212.242.1: bytes=32 time=560ms TTL=56
Reply from 10.212.242.1: bytes=32 time=569ms TTL=56
Reply from 10.212.242.1: bytes=32 time=577ms TTL=56
Reply from 10.212.242.1: bytes=32 time=548ms TTL=56
Reply from 10.212.242.1: bytes=32 time=554ms TTL=56
Reply from 10.212.242.1: bytes=32 time=579ms TTL=56
Reply from 10.212.242.1: bytes=32 time=533ms TTL=56
Reply from 10.212.242.1: bytes=32 time=551ms TTL=56
```

```
Reply from 10.212.242.1: bytes=32 time=590ms TTL=56

Ping statistics for 10.212.242.1:
    Packets: Sent = 11, Received = 11, Lost = 0 (0% loss),

Approximate round trip times in milli-seconds:
    Minimum = 533ms, Maximum = 590ms, Average = 561ms
```

Lista de sites acessados:

www.globo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.mg.gov.br - ok

Responsável pelo teste de navegação:

Nome: Wagner da Silva barros

Telefone: 3899810-0791

Função: Diretor Masp: 886507-3

Funcionamento: 17:00 às 21:00h