


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior Operadora/Cliente: Ronaldo Candido

GRE/Prodemge: João Antinossi Responsável/cliente : Agres Cristiano de Souza

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-CORO-220162MbpsVSAT



PRTG Traffic Grapher V6.2.0.907 - 14/10/2017 00:26:48

dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

ldx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E Yes

Satellite (DVB) Receiver Status Rx State : On DVB State : Forward link up Network : 65281, Prodemge@Vodanet Frequency: 12.176406 GHz Symbol Rate : 4.882962 Msps S2 ModCod - receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6 Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type: MPEG-TS Roll off : 0.20 SNR : 17.0 dB Input Power : -30 dBm # dvb tx show Satellite (DVB) TX Configuration Auto start : Enabled IDU Output Power : -20 dBm IDU Max Output Power: 0.0 dBm ODU Output Power : 33.2 dBm

EIRP : 46.5 dBW

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux

Header Compression: UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2)

IDU Output Power : -20.6 dBm

ODU Output Power : 33.4 dBm

EIRP : 46.7 dBW

Es/No : 13.5 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction: -374 us (281754 us)

Frequency correction: 50 Hz

device show

System Information:

Name : SEE-CORO-22016

Location : CONCEL O DO MATO DENTRO/MG

Contact :

System Up time : 0 days, 04:15:26

CPU Load : 11%

System time(UTC) : 18 October 2017 13:20:32

Broadcast Message : not set

HW:

Model : SatLink 2000

HW ID : 120033

Main board ID : 120026 R6.2

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:5b:21

Satellite (DVB) : 00:20:0e:10:5b:21

arp show

NetAddr State MacAddr If 10.212.88.2 Dynamic 80:ee:73:a4:e2:ba 1 Pinging 10.212.88.1 with 32 bytes of data:

Reply from 10.212.88.1: bytes=32 time=550ms TTL=56

Reply from 10.212.88.1: bytes=32 time=557ms TTL=56

Reply from 10.212.88.1: bytes=32 time=573ms TTL=56

Reply from 10.212.88.1: bytes=32 time=545ms TTL=56

Reply from 10.212.88.1: bytes=32 time=596ms TTL=56

Reply from 10.212.88.1: bytes=32 time=590ms TTL=56

Reply from 10.212.88.1: bytes=32 time=586ms TTL=56

Reply from 10.212.88.1: bytes=32 time=580ms TTL=56

Reply from 10.212.88.1: bytes=32 time=571ms TTL=56

Reply from 10.212.88.1: bytes=32 time=566ms TTL=56

Ping statistics for 10.212.88.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),

Approximate round trip times in milli-seconds:

Minimum = 545ms, Maximum = 596ms, Average = 571ms

Sites acessados

www.globo.com ok

www.yahoo.com.br- ok

www.hotmail.com- ok

<u>www.google.com</u> – ok

www.prodemge.gov.br - ok

Nome do responsável: Agres Cristiano de Souza	
MASP: 1097797-3	
Telefone: (31) 99915210	
Cargo: Diretora Horário de funcionamento: 7:00 as 16:15	
Horario de funcionamento. 7:00 as 16:15	