


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Paulo de Tarso Operadora/Cliente: Eduardo Tadra

Responsável/cliente: Onofre Martinho de Carvalho GRE/Prodemge: João Antinossi

> Consórcio VSAT-ID Plataforma Porta kbps EMC/Vodanet SEE-ANAS-22591 2048/1024 **VSAT**



PRTG Traffic Grapher V6.2.0.907 - 3/11/2017 16:04:13

Satellite (DVB) RX Configuration _____

Auto start : Enabled

Auto start

Max Traffic MODCOD

RY watchdog

. Enactor

: 23 16APSK-9/10

: 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 0 0.0 E * 0 0

Yes

Satellite (DVB) Receiver Status _____

Rx State : On

DVB State : Forward link up

: 65281, Prodemge@Vodanet Network

Frequency : 12.176389 GHz Symbol Rate : 4.882901 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.7 dB Input Power : -39 dBm

```
Satellite (DVB) TX Configuration
 _____
                   : Enabled
Auto start
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
                    : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -13.4 dBm
ODU Output Power : 33.1 dBm
EIRP
                    : 46.4 dBW
Es/No
                    : 14.0 dB
{\tt Header\ Compression} : Disabled - HC for RCS2 not supported by HUB
Timing correction : -335 us (281663 us)
Frequency correction: 120 Hz
System Information:
   Name
                       : SEE-ANAS-22591
    Location
                        : Ant¦nio Dias
    Contact
    System Up time : 0 days, 01:08:20 CPU Load : 7%
    System time(UTC) : 03 November 2017 15:02:56
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                       : 120033
                       : 120026 R6.1
    Main board ID
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:4a:2f
Satellite (DVB) : 00:20:0e:10:4a:2f
   Ethernet (LAN)
Reply from 10.214.182.1: bytes=32 time=553ms TTL=56
Reply from 10.214.182.1: bytes=32 time=582ms TTL=56
Reply from 10.214.182.1: bytes=32 time=604ms TTL=56
Reply from 10.214.182.1: bytes=32 time=593ms TTL=56
Reply from 10.214.182.1: bytes=32 time=537ms TTL=56
Reply from 10.214.182.1: bytes=32 time=543ms TTL=56
Reply from 10.214.182.1: bytes=32 time=539ms TTL=56
Reply from 10.214.182.1: bytes=32 time=567ms TTL=56
Reply from 10.214.182.1: bytes=32 time=559ms TTL=56
Reply from 10.214.182.1: bytes=32 time=578ms TTL=56
Ping statistics for 10.214.182.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 537ms, Maximum = 604ms, Average = 565ms
          State MacAddr
NetAddr
   10.214.182.2 Dynamic b8:70:f4:6e:b3:ab 1
```

Lista de sites acessados:
www.globo.com – ok
<u>www.yahoo.com</u> – ok
<u>www.hotmail.com</u> – ok
www.google.com – ok
www.educacao.mg.gov.br – ok
www.prodemge.gov.br – ok
Responsável pelo teste de navegação:
Nome: Onofre Martinho de Carvalho
Função: Diretor
telefone : 31-38431275
MASP: 825506-9
horario das 7:00 as 22:30