TERMO DE ACEITE TÉCNICO

EMC — EMERGING MARKETS COMMUNICATIONS

Solicitante: VIVO- Projeto Escolas Rurais

NOC/Operador: Guilherme Cunha

Cliente: VIVO

Empresa	VSAT-ID	Link kbps	Plataforma
EMC Brasil	VIVO-PER-31157643-MG	256k/128k	VSAT

Telnet 10.29.65.185

```
- SW ID 120208, Revision 16.0.1 Build 57
#
Satellite (DVB) TX Configuration
---------------------------------
Auto start              : Enabled
IDU Output Power        : -20 dBm
IDU Max Output Power    : 0.0 dBm
ODU Output Power        : max
EIRP                    : max
Default CW Frequency    : 0.000000 GHz
ATM mode                : VC-Mux
Header Compression      : None


Satellite (DVB) Transmitter Status
----------------------------------
State                   : On  (DUB-RCS2)
IDU Output Power        : -9.8 dBm
ODU Output Power        : 32.7 dBm
EIRP                    : 46.0 dBW
Es/No                   : 13.5 dB
Header Compression      : Disabled
Timing correction       : -171 us (249377 us)
Frequency correction    : 110 Hz
#
```

SpeedOf.Me, Internet speed ... accurate online bandwidth test. It works well on iPhone, iPad, Android, Windows and other mobile

Download
Upload

0.1

0

18:38:10   18:38:20   18:38:30   18:38:40

Time

History

Speed (Mbps)

0.5

0

16. Dec   08:00   16:00   17. Dec

Date

Test Again   Share

Liked it? Spread the word: 28.2K

API | About | How It Works | Privacy | Terms | Help Center
Copyright © 2011-2017 SPEED OF ME | v2.9.18

domingo, 17 de dezembro de 2017
◄ dezembro de 2017 ►
D S T Q Q S S
26 27 28 29 30 1 2
 3 4 5 6 7 8 9
10 11 12 13 14 15 16
17 18 19 20 21 22 23
24 25 26 27 28 29 30
31 1 2 3 4 5 6
18:40:24
Alterar configurações de data e hora...

18:40
17/12/2017

Prompt de Comando

```
Microsoft Windows [versão 6.3.9600]
(c) 2013 Microsoft Corporation. Todos os direitos reservados.

C:\Users\tecnico joao>ping 8.8.8.8 -t

Disparando 8.8.8.8 com 32 bytes de dados:
Resposta de 8.8.8.8: bytes=32 tempo=2239ms TTL=49
Resposta de 8.8.8.8: bytes=32 tempo=2489ms TTL=49
Resposta de 8.8.8.8: bytes=32 tempo=1082ms TTL=49
Resposta de 8.8.8.8: bytes=32 tempo=2464ms TTL=49
Resposta de 8.8.8.8: bytes=32 tempo=1137ms TTL=49
Resposta de 8.8.8.8: bytes=32 tempo=1060ms TTL=49
Resposta de 8.8.8.8: bytes=32 tempo=1069ms TTL=49
Resposta de 8.8.8.8: bytes=32 tempo=1079ms TTL=49
Resposta de 8.8.8.8: bytes=32 tempo=963ms TTL=49
Resposta de 8.8.8.8: bytes=32 tempo=1143ms TTL=49
Resposta de 8.8.8.8: bytes=32 tempo=1072ms TTL=49
Resposta de 8.8.8.8: bytes=32 tempo=1075ms TTL=49
Resposta de 8.8.8.8: bytes=32 tempo=1791ms TTL=49
Resposta de 8.8.8.8: bytes=32 tempo=1077ms TTL=49
Resposta de 8.8.8.8: bytes=32 tempo=1067ms TTL=49

Estatísticas do Ping para 8.8.8.8:
    Pacotes: Enviados = 15, Recebidos = 15, Perdidos = 0 (0% de
    perda),
Aproximar um número redondo de vezes em milissegundos:
    Mínimo = 963ms, Máximo = 2489ms, Média = 1387ms
Control-C
^C
C:\Users\tecnico joao>arp -a

Interface: 10.29.65.186 --- 0x7
  Endereço IP           Endereço físico       Tipo
  10.29.65.185          00-20-0e-10-5b-e1     dinâmico
  10.29.65.191          ff-ff-ff-ff-ff-ff     estático
  224.0.0.2             01-00-5e-00-00-02     estático
  224.0.0.22            01-00-5e-00-00-16     estático
  224.0.0.251           01-00-5e-00-00-fb     estático
  224.0.0.252           01-00-5e-00-00-fc     estático
  239.255.255.250       01-00-5e-7f-ff-fa     estático
  255.255.255.255       ff-ff-ff-ff-ff-ff     estático

C:\Users\tecnico joao>
```

Novo Documento ...

Novo Documento ...

domingo, 17 de dezembro de 2017
◄ dezembro de 2017 ►
D S T Q Q S S
26 27 28 29 30 1 2
 3 4 5 6 7 8 9
10 11 12 13 14 15 16
17 18 19 20 21 22 23
24 25 26 27 28 29 30
31 1 2 3 4 5 6
18:42:13
Alterar configurações de data e hora...

18:42
17/12/2017