

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Paulo de Tarso Operadora/Cliente: Gustavo de Oliveira da Silva

GRE/Prodemge: João Antinossi Responsável/cliente: Warley Evangelista de Brito

> Consórcio VSAT-ID Porta kbps Plataforma





PRTG Traffic Grapher V6.2.0.907 - 3/11/2017 13:05:50

Satellite (DVB) RX Configuration _____

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10 RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 0 0.0 E * 0 0

Yes

Satellite (DVB) Receiver Status ______

Rx State : On

: Forward link up DVB State

Network : 65281, Prodemge@Vodanet

Frequency : 12.176465 GHz Symbol Rate : 4.883012 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On : Short Frame length DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.1 dB Input Power : -29 dBm

```
Satellite (DVB) TX Configuration
_____
                   : Enabled
Auto start
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                   : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode
                   : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
-----
State : On (DVB-RCS2)
IDU Output Power : -18.4 dBm
ODU Output Power : 33.1 dBm
EIRP
                   : 46.4 dBW
Es/No
                   : 14.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -476 us (281673 us)
Frequency correction: 20 Hz
System Information:
   Name
                       : SEE-JAIA-22150
    Location
                       : JANUARIA - MG
    Contact
                       :
   Broadcast Message : not set
HW:
    Model
                       : SatLink 2000
    HW ID
                       : 120033
    Main board ID
                       : 120026 R6.2
MAC addresses:
   Ethernet (LAN)
                    : 00:20:0e:10:54:f2
    Satellite (DVB)
                       : 00:20:0e:10:54:f2
Pinging 10.148.1.58 with 32 bytes of data:
Reply from 10.148.1.58: bytes=32 time=578ms TTL=62
Reply from 10.148.1.58: bytes=32 time=554ms TTL=62
Reply from 10.148.1.58: bytes=32 time=575ms TTL=62
Reply from 10.148.1.58: bytes=32 time=557ms TTL=62
Reply from 10.148.1.58: bytes=32 time=561ms TTL=62
Reply from 10.148.1.58: bytes=32 time=563ms TTL=62
Reply from 10.148.1.58: bytes=32 time=566ms TTL=62
Reply from 10.148.1.58: bytes=32 time=577ms TTL=62
Reply from 10.148.1.58: bytes=32 time=558ms TTL=62
Reply from 10.148.1.58: bytes=32 time=529ms TTL=62
Ping statistics for 10.148.1.58:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 529ms, Maximum = 578ms, Average = 561ms
NetAddr
         State MacAddr
   10.212.203.2 Dynamic 64:1c:67:61:83:29
```

Lista de sites acessados:

www.globo.com - ok
www.yahoo.com - ok
www.hotmail.com - ok
www.google.com - ok
www.educacao.mg.gov.br - ok

www.prodemge.gov.br – ok

Responsável pelo teste de navegação: Nome: Warley Evangelista de Brito

Função: Diretor

Telefone: (38) 99936-1289

MASP: 11125820

Expediente 07:00 as 22:00