


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Hernan Alves Operadora/Cliente: Jean Polini

GRE/Prodemge: João Antinossi Responsável/cliente: Marcia Cristina Pereira Silva

> Consórcio **VSAT-ID** Porta kbps Plataforma EMC/Vodanet SEE-URIA-22287 2Mbps **VSAT**



Satellite (DVB) RX Configuration ______ Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

12.176420 DVB-S2 104 0 0.0 E * 0 0 4.883300

Yes

Satellite (DVB) Receiver Status

Rx State : On

: Forward link up DVB State

Network : 65281, Prodemge@Vodanet

Frequency : 12.176265 GHz Symbol Rate : 4.882989 Msps

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

: On Pilot : ACM : Short Frame length DVB S2 Mode DVB S2 Stream type : MPEG-TS Roll off : 0.20 : 16.2 dB SNR Input Power : -28 dBm

dvb tx show

```
Satellite (DVB) TX Configuration
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                     : 46.5 dBW
Default CW Frequency: 0.000000 GHz
                     : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -21.3 dBm
ODU Output Power : 32.9 dBm
                     : 46.2 dBW
EIRP
Es/No
                     : 11.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{: Disabled} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -364 us (282105 us)
Frequency correction: 180 Hz
# device show
System Information:
    Name
                         : SEE-URIA-22287
    Location
                          : URUCUIA - MG
    Contact
    System Up time : 0 days, 00:27:28 CPU Load : 18%
    System time(UTC) : 01 November 2017 16:36:51 Broadcast Message : not set
HW:
    Model
                         : SatLink 2000
                         : 120033
    HW ID
    Main board ID
                         : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:54:6a
Satellite (DVB) : 00:20:0e:10:54:6a
# arp show
   NetAddr
                 State MacAddr
    10.213.86.2 Dynamic 64:1c:67:62:2e:12 1
#
Pinging 10.213.86.1 with 32 bytes of data:
Reply from 10.213.86.1: bytes=32 time=574ms TTL=56
Reply from 10.213.86.1: bytes=32 time=548ms TTL=56
Reply from 10.213.86.1: bytes=32 time=558ms TTL=56
Reply from 10.213.86.1: bytes=32 time=555ms TTL=56
Reply from 10.213.86.1: bytes=32 time=549ms TTL=56
Reply from 10.213.86.1: bytes=32 time=555ms TTL=56
Reply from 10.213.86.1: bytes=32 time=547ms TTL=56
Reply from 10.213.86.1: bytes=32 time=641ms TTL=56
Reply from 10.213.86.1: bytes=32 time=564ms TTL=56
Reply from 10.213.86.1: bytes=32 time=548ms TTL=56
Reply from 10.213.86.1: bytes=32 time=543ms TTL=56
Ping statistics for 10.213.86.1:
    Packets: Sent = 11, Received = 11, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 543ms, Maximum = 641ms, Average = 562ms
```

Lista de sites acessados:

www.globo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.mg.gov.br - ok

Responsável pelo teste de navegação: Nome: Marcia Cristina Pereira Silva

Função: Vice Diretora Telefone: 38 36349211

MASP 814 865-2

Funcionamento: 07:00 às 23:00h