


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Gilvan Junior

GRE/Prodemge: João Antinossi Responsável/cliente: Maria Aparecida da Silva Ferreira

> Porta kbps Plataforma Consórcio **VSAT-ID VSAT** EMC/Vodanet SEE-TAIM-23168 2Mbps



## Satellite (DVB) RX Configuration \_\_\_\_\_

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

: 15 minute RX watchdog

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

\* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

0.000000 DVB-S2 2 0 0.0 E 0.000000 1 1

No

## Satellite (DVB) Receiver Status

Rx State : On

: Forward link up DVB State

: 65281, Prodemge@Vodanet Network

: 65281, Prodei : 12.176527 GHz Frequency Symbol Rate : 4.883025 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS : 0.20 Roll off : 15.7 dB SNR Input Power : -28 dBm

```
Satellite (DVB) TX Configuration
 ______
Auto start
                                          : Enabled
IDU Output Power : -21 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 32.7 dBm
EIRP
                                          : 46.0 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -18.7 dBm
ODU Output Power : 32.9 dBm
EIRP
                                           : 46.2 dBW
Es/No
                                           : 13.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -250 us (281187 us)
Frequency correction: 120 Hz
System Information:
        Name
                                                  : SEE-TAIM-23168
         Location
                                                   : Tarumirim - MG
         Contact
        System Up time : 0 days, 00:10:06 CPU Load : 15%
        System time (UTC) : 01 December 2017 17:05:53
         Broadcast Message : not set
HW:
        Model
                                                   : SatLink 2000
         HW ID
                                                   : 120033
         Main board ID
                                                  : 120026 R6.2
        converse convence converse converse converse converse converse converse convers
MAC addresses:
        Ethernet (LAN)
NetAddr
                           State MacAddr
       10.214.174.2 Dynamic e8:9a:8f:b7:bd:4a 1
Pinging 10.214.174.1 with 32 bytes of data:
Reply from 10.214.174.1: bytes=32 time=595ms TTL=56
Reply from 10.214.174.1: bytes=32 time=529ms TTL=56
Reply from 10.214.174.1: bytes=32 time=532ms TTL=56
Reply from 10.214.174.1: bytes=32 time=582ms TTL=56
Reply from 10.214.174.1: bytes=32 time=530ms TTL=56
Reply from 10.214.174.1: bytes=32 time=629ms TTL=56
Reply from 10.214.174.1: bytes=32 time=528ms TTL=56
Reply from 10.214.174.1: bytes=32 time=603ms TTL=56
Reply from 10.214.174.1: bytes=32 time=532ms TTL=56
Reply from 10.214.174.1: bytes=32 time=585ms TTL=56
Ping statistics for 10.214.174.1:
         Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
         Minimum = 528ms, Maximum = 629ms, Average = 564ms
```

Lista de sites acessados:
<u>www.globo.com</u> – ok
<u>www.yahoo.com</u> – ok
<u>www.hotmail.com</u> – ok
<u>www.google.com</u> – ok
www.educacao.mg.gov.br – ok
www.prodemge.gov.br – ok
Responsável pelo teste de navegação:
Nome: Maria Aparecida da Silva Ferreira
Função: Secretaria
MASP: 514494-4
Telefone: 33-999841858
Funcionamento: 07:00h às 22:00h