


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Jean Polini

Responsável/cliente: Edileia de Deus Melo **GRE/Prodemge:** João Antinossi

> Consórcio Plataforma **VSAT-ID** Porta kbps EMC/Vodanet VSAT SEE-GOIA-22031 2Mbps



PRTG Traffic Grapher V6.2.0.907 - 5/10/2017 22:20:01

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

12.176420 DVB-S2 104 * 0 0 4.883300 0 0.0 E

Yes

0 0.0 E 1 1 16.667000 11.962753 DVB-S2 2

Yes

Satellite (DVB) Receiver Status _____

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

: 12.176294 GHz Frequency Symbol Rate : 4.882920 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

: On Pilot Frame length : Short : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 14.0 dB Input Power : -38 dBm

```
Satellite (DVB) TX Configuration
______
                    : Enabled
Auto start
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                     : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode
                     : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -18.8 dBm
ODU Output Power : 33.0 dBm
EIRP
                     : 46.3 dBW
                     : 14.5 dB
Es/No
\hbox{{\tt Header Compression}} \quad \hbox{: Disabled} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -186 us (281901 us)
Frequency correction: 80 Hz
System Information:
    Name
                         : SEE-GOIA-22031
    Location
                         : Gouveia
    Contact
    System Up time : 0 days, 00:21:16
CPU Load : 24%
System time(UTC) : 05 October 2017 20:28:41
    Broadcast Message : not set
HW:
    Model
                         : SatLink 2000
    HW ID
                         : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:52:08
Satellite (DVB) : 00:20:0e:10:52:08
Disparando 10.148.0.18 com 32 bytes de dados:
Resposta de 10.148.0.18: bytes=32 tempo=550ms TTL=57
Resposta de 10.148.0.18: bytes=32 tempo=584ms TTL=57
Resposta de 10.148.0.18: bytes=32 tempo=558ms TTL=57
Resposta de 10.148.0.18: bytes=32 tempo=570ms TTL=57
Resposta de 10.148.0.18: bytes=32 tempo=584ms TTL=57
Resposta de 10.148.0.18: bytes=32 tempo=534ms TTL=57
Resposta de 10.148.0.18: bytes=32 tempo=554ms TTL=57
Resposta de 10.148.0.18: bytes=32 tempo=570ms TTL=57
Resposta de 10.148.0.18: bytes=32 tempo=558ms TTL=57
Resposta de 10.148.0.18: bytes=32 tempo=538ms TTL=57
Estatísticas do Ping para 10.148.0.18:
    Pacotes: Enviados = 10, Recebidos = 10, Perdidos = 0 (0% de
             perda),
Aproximar um número redondo de vezes em milissegundos:
    Mínimo = 534ms, Máximo = 584ms, Média = 560ms
```

Lista de sites acessados:
www.globo.com – ok
www.hotmail.com – ok
www.google.com – ok
www.educacao.mg.gov.br – ok
Responsável pelo teste de navegação: Nome: Edileia de Deus Melo Função: Secretária dentidade: MG 4213621