

TERMO DE ACEITE TÉCNICO

Plataforma

VSAT

Solicitante: PRODEMGE / SEE


NOC/Operadora: Ermínio Junior Operadora/Cliente Jean Polini

GRE/Prodemge: João Antinossi

Responsável/cliente SORAYA LAURE SANDER

ConsórcioVSAT-IDPorta kbpsEMC/VodanetSEE-CAAI-229222Mbps

Port eth0 SEE-CAAI-22922 (10.215.102.1)



dvb tx show

Satellite (DVB) TX Configuration

Auto start : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2) IDU Output Power : -19.8 dBm

Es/No : 13.5 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction : -190 us (280486 us)

Frequency correction: 170 Hz

dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Enable

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176381 GHz Symbol Rate : 4.882988 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short
DVB S2 Mode : ACM
DVB S2 Stream type : MPEG-TS

Roll off : 0.20 SNR : 16.1 dB Input Power : -41 dBm

arp show

NetAddr State MacAddr If 10.215.102.2 Dynamic 64:1c:67:62:2e:12 1

device show System Information:

> Name : SEE-CAAI-22922 Location : Carai - MG

Contact :

System Up time : 0 days, 00:03:21

CPU Load : 17%

System time(UTC) : 25 November 2017 19:04:54

Broadcast Message : not set

HW:

Model : SatLink 2000 HW ID : 120033 Main board ID : 120026 R6.1

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:48:e8 Satellite (DVB) : 00:20:0e:10:48:e8

Pinging 10.215.102.1 with 32 bytes of data:

Reply from 10.215.102.1: bytes=32 time=565ms TTL=56 Reply from 10.215.102.1: bytes=32 time=597ms TTL=56 Reply from 10.215.102.1: bytes=32 time=524ms TTL=56 Reply from 10.215.102.1: bytes=32 time=573ms TTL=56 Reply from 10.215.102.1: bytes=32 time=573ms TTL=56 Reply from 10.215.102.1: bytes=32 time=575ms TTL=56 Reply from 10.215.102.1: bytes=32 time=575ms TTL=56 Reply from 10.215.102.1: bytes=32 time=571ms TTL=56 Reply from 10.215.102.1: bytes=32 time=551ms TTL=56 Reply from 10.215.102.1: bytes=32 time=562ms TTL=56 Reply from 10.215.102.1: bytes=32 time=582ms TTL=56

Ping statistics for 10.215.102.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss), Approximate round trip times in milli-seconds: Minimum = 524ms, Maximum = 597ms, Average = 569ms www.hotmail.com

www.google.com

www.prodemge.gov.br

www.globo.com

www.youtube.com

RESPONSAVEL: SORAYA LAURE SANDER

CARGO: SUPERVISORA

MASP:1276203-5 TEL:33 984003496

HORARIO DE FUNCINAMENTO: 07:00 AS 22;15

MODEM INST :EM BANDEJA NA SALA DOS PROFESSORES E CONECTADO A UM PC DA SAL