

TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Jean Polini

Responsável/cliente: Vanderlei Cordeiro Farias GRE/Prodemge: João Antinossi

> Consórcio **VSAT-ID** Porta kbps Plataforma EMC/Vodanet SEE-PEUZ-22194 2Mbps **VSAT**



Satellite (DVB) RX Configuration -----

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

12.176420 DVB-S2 104 0 0.0 E * 0 0 4.883300

Yes

11.962753 DVB-S2 2 0 0.0 E 16.667000 1 1

Yes

Satellite (DVB) Receiver Status

Rx State : On

: Forward link up DVB State

: 65281, Prodemge@Vodanet Network

: 65281, Prode : 12.176549 GHz Frequency : 4.882910 Msps Symbol Rate

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short : ACM DVB S2 Mode DVB S2 Stream type : MPEG-TS : 0.20 Roll off : 16.0 dB SNR Input Power : -34 dBm

```
Satellite (DVB) TX Configuration
_____
Auto start
                   : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
                   : 46.5 dBW
EIRP
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
: On (DVB-I
IDU Output Power : -10.8 dBm
ODU Output Power : 32.9 dBm
                    : On (DVB-RCS2)
State
EIRP
                    : 46.2 dBW
Es/No
                    : 12.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{: Disabled} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -429 us (281414 us)
Frequency correction: 20 Hz
System Information:
   Name
                       : SEE-PEUZ-22194
    Location
                        : PEDRAS DE MARIA DA CRUZ - MG
    Contact
   System Up time : 0 days, 00:52:01 CPU Load : 23%
    System time(UTC) : 27 October 2017 11:06:33
    Broadcast Message : not set
HW:
                       : SatLink 2000
    Model
                       : 120033
    HW ID
    Main board ID
                       : 120026 R6.1
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:4a:3c
Satellite (DVB) : 00:20:0e:10:4a:3c
NetAddr
          State MacAddr
   10.212.247.2 Dynamic 64:1c:67:62:2e:12
Pinging 10.212.247.1 with 32 bytes of data:
Reply from 10.212.247.1: bytes=32 time=537ms TTL=56
Reply from 10.212.247.1: bytes=32 time=571ms TTL=56
Reply from 10.212.247.1: bytes=32 time=550ms TTL=56
Reply from 10.212.247.1: bytes=32 time=550ms TTL=56
Reply from 10.212.247.1: bytes=32 time=551ms TTL=56
Reply from 10.212.247.1: bytes=32 time=713ms TTL=56
Reply from 10.212.247.1: bytes=32 time=538ms TTL=56
Reply from 10.212.247.1: bytes=32 time=543ms TTL=56
Reply from 10.212.247.1: bytes=32 time=875ms TTL=56
Reply from 10.212.247.1: bytes=32 time=546ms TTL=56
Ping statistics for 10.212.247.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 537ms, Maximum = 875ms, Average = 597ms
```

Lista de sites acessados:

<u>www.globo.com</u> – ok

www.yahoo.com - ok

<u>www.hotmail.com</u> – ok

www.google.com - ok

www.educacao.mg.gov.br - ok

www.prodemge.gov.br - ok

Responsável pelo teste de navegação: Nome: Vanderlei Cordeiro Farias

Função: Vice-Diretor

Identidade: MASP 845429-0

Telefone: 38- 3622-4277

Horário de funcionamento – 07:00 as 21:30