



SatLink 2000

- Main board ID 120026, Revision R6.2
- SW ID 120208, Revision 16.0.1 Build 57

dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E Yes 1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency: 12.176193 GHz

Symbol Rate : 4.882986 Msps

S2 ModCod

- receiving : 4 QPSK-1/2

- current max : 21 16APSK-5/6

Pilot : On

Frame length : Short DVB S2 Mode : ACM

DVB S2 Stream type: MPEG-TS

Roll off : 0.20 SNR : 14.8 dB Input Power : -35 dBm

dvb tx show

Satellite (DVB) TX Configuration

Auto start : Enabled IDU Output Power : -21 dBm IDU Max Output Power: 0.0 dBm ODU Output Power : 33.7 dBm

EIRP : 47.0 dBW

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2) IDU Output Power : -17.6 dBm ODU Output Power : 33.8 dBm

EIRP : 47.1 dBW Es/No : 13.5 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction : -289 us (281193 us)

Frequency correction: 150 Hz

arp show

NetAddr State MacAddr If 10.213.45.2 Dynamic e8:9a:8f:b7:bd:4a 1

device show

System Information:

Name : SEE-MOIA-22246

Location : So Jo das Misses - MG

Contact :

System Up time : 0 days, 00:20:13

CPU Load : 15%

System time(UTC) : 31 October 2017 17:46:32

Broadcast Message : not set

HW:

Model : SatLink 2000 HW ID : 120033

Main board ID : 120026 R6.2

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:58:58 Satellite (DVB) : 00:20:0e:10:58:58

Pinging 10.213.45.1 with 32 bytes of data:

Reply from 10.213.45.1: bytes=32 time=524ms TTL=56 Reply from 10.213.45.1: bytes=32 time=520ms TTL=56 Reply from 10.213.45.1: bytes=32 time=532ms TTL=56 Reply from 10.213.45.1: bytes=32 time=534ms TTL=56 Reply from 10.213.45.1: bytes=32 time=546ms TTL=56 Reply from 10.213.45.1: bytes=32 time=555ms TTL=56 Reply from 10.213.45.1: bytes=32 time=524ms TTL=56 Reply from 10.213.45.1: bytes=32 time=560ms TTL=56 Reply from 10.213.45.1: bytes=32 time=537ms TTL=56 Reply from 10.213.45.1: bytes=32 time=532ms TTL=56 Reply from 10.213.45.1: bytes=32 time=532ms TTL=56

Ping statistics for 10.213.45.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),

Approximate round trip times in milli-seconds:

Minimum = 520ms, Maximum = 560ms, Average = 555ms

www.globo.com

www.yahoo.com.br

www.hotmail.com

www.google.com

www.prodemge.gov.br

Responsável	Vanild Gonçalves de Jesus
Cargo	Vice-Diretora
Identidade	450498-1
Telefone	038-9-9826-3840
Funcionamento	07:00 até 17:20