

## TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Ronaldo Candido

GRE/Prodemge: João Antinossi Responsável/cliente: Viviane Carvalho de Macedo

> Porta kbps Plataforma Consórcio **VSAT-ID** EMC/Vodanet **VSAT** SEE-NORO-22937 2Mbps

## Port eth0 on SEE-NORO-22937 (10.215.130.1)



Satellite (DVB) RX Configuration \_\_\_\_\_ Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

12.176420 DVB-S2 104 0 0.0 E \* 0 0 4.883300

Yes

Satellite (DVB) Receiver Status

Rx State : On

: Forward link up DVB State

Network : 65281, Prodemge@Vodanet

: 65281, Proder : 12.176428 GHz Frequency Symbol Rate : 4.882995 Msps

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

: On Pilot Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 : 14.8 dB SNR Input Power : -36 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -14.7 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Es/No
                    : 13.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -192 us (280729 us)
Frequency correction: 120 Hz
System Information:
    Name
                       : SEE-NORO-22937
    Location
                        : Novo Cruzeiro - MG
    Contact
    System Up time : 0 days, 00:04:03 CPU Load : 26%
    System time(UTC) : 20 November 2017 19:24:32
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                       : 120026 R6.1
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:48:d6
Satellite (DVB) : 00:20:0e:10:48:d6
    Ethernet (LAN)
NetAddr
             State MacAddr
   10.215.130.2 Dynamic 80:ee:73:a4:e2:ba 1
Pinging 10.215.130.1 with 32 bytes of data:
Reply from 10.215.130.1: bytes=32 time=602ms TTL=56
Reply from 10.215.130.1: bytes=32 time=671ms TTL=56
Reply from 10.215.130.1: bytes=32 time=563ms TTL=56
Reply from 10.215.130.1: bytes=32 time=549ms TTL=56
Reply from 10.215.130.1: bytes=32 time=525ms TTL=56
Reply from 10.215.130.1: bytes=32 time=611ms TTL=56
Reply from 10.215.130.1: bytes=32 time=591ms TTL=56
Reply from 10.215.130.1: bytes=32 time=568ms TTL=56
Reply from 10.215.130.1: bytes=32 time=531ms TTL=56
Reply from 10.215.130.1: bytes=32 time=682ms TTL=56
Ping statistics for 10.215.130.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 525ms, Maximum = 682ms, Average = 589ms
```

Lista de sites acessados:
www.globo.com – ok
www.yahoo.com – ok
www.hotmail.com – ok
www.google.com – ok
www.educacao.mg.gov.br – ok
www.prodemge.gov.br – ok
Responsável pelo teste de navegação:
Nome: Viviane Carvalho de Macedo
Função: Diretora
MASP: 1008502-5
Telefone: 33-98825-4550
Funcionamento: 07:00h às 18:00h