

## TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Ederson Martins

GRE/Prodemge: João Antinossi Responsável/cliente: Matia Mirtes Gomes Bandeira

> Porta kbps Plataforma Consórcio **VSAT-ID VSAT** EMC/Vodanet SEE-SASO-22589 2Mbps





## Satellite (DVB) RX Configuration \_\_\_\_\_

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

12.176420 DVB-S2 104 0 0.0 E \* 0 0 4.883300

Yes

11.962753 DVB-S2 2 0 0.0 E 1 1 16.667000

Yes

## Satellite (DVB) Receiver Status

Rx State : On

: Forward link up DVB State

: 65281, Prodemge@Vodanet Network

: 65281, Proder : 12.176618 GHz Frequency Symbol Rate : 4.883035 Msps

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot
Frame length : Snor
ACM Pilot : On : Short DVB S2 Stream type : MPEG-TS : 0.20 Roll off : 17.4 dB SNR Input Power : -37 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -21 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
: On (DVB-RCS2)

IDU Output Power : -18.0 dBm

ODU Output Power : 33.0 dBm

EIRP
______
Es/No
                    : 14.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -365 us (280364 us)
Frequency correction: -10 Hz
System Information:
    Name
                       : SEE-SASO-22589
    Location
                        : SÃO JOÃO DO PARAÍSO - MG
    Contact
    System Up time : 0 days, 00:06:11 CPU Load : 18%
    System time (UTC) : 09 November 2017 12:11:35
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.1
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:48:cc
Satellite (DVB) : 00:20:0e:10:48:cc
NetAddr
           State MacAddr
    10.214.24.2 Dynamic 1c:39:47:5b:e2:48 1
Pinging 10.214.24.1 with 32 bytes of data:
Reply from 10.214.24.1: bytes=32 time=548ms TTL=56
Reply from 10.214.24.1: bytes=32 time=563ms TTL=56
Reply from 10.214.24.1: bytes=32 time=574ms TTL=56
Reply from 10.214.24.1: bytes=32 time=565ms TTL=56
Reply from 10.214.24.1: bytes=32 time=606ms TTL=56
Reply from 10.214.24.1: bytes=32 time=699ms TTL=56
Reply from 10.214.24.1: bytes=32 time=562ms TTL=56
Reply from 10.214.24.1: bytes=32 time=539ms TTL=56
Reply from 10.214.24.1: bytes=32 time=533ms TTL=56
Reply from 10.214.24.1: bytes=32 time=530ms TTL=56
Ping statistics for 10.214.24.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 530ms, Maximum = 699ms, Average = 571ms
```

## Lista de sites acessados:

www.globo.com - ok

<u>www.yahoo.com</u> – ok

 $\underline{www.hotmail.com} - ok$ 

www.google.com – ok

<u>www.educacao.mg.gov.br</u> – ok <u>www.prodemge.gov.br</u> – ok

Responsável pelo teste de navegação:

Nome: Matia Mirtes Gomes Bandeira Fernandes

Função: Diretora MASP: 975471-4

Telefone: 38-99955-2943

Funcionamento: 07:00 às 22:00h