


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Hernan Alves Operadora/Cliente: Gilvan Junior

GRE/Prodemge: João Antinossi Responsável/cliente: Franciele Pereira de Sousa

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-SAES-222652MbpsVSAT



Satellite (DVB) RX Configuration
----Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176178 GHz Symbol Rate : 4.882969 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short

DVB S2 Mode : ACM

DVB S2 Stream type : MPEG-TS

Roll off : 0.20

SNR : 15.3 dB

Input Power : -33 dBm

```
Satellite (DVB) TX Configuration
_____
Auto start
                    : Enabled
IDU Output Power : -21 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.5 dBm EIRP : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -15.3 dBm
ODU Output Power : 33.6 dBm
EIRP
                    : 46.6 dBW
                    : 14.5 dB
Es/No
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -372 us (281232 us)
Frequency correction: 90 Hz
System Information:
   Name
                        : SEE-SAES-22265
    Location
                        : SO JOO DAS MISSES - MG
    Contact
    System Up time : 0 days, 00:03:53 CPU Load : 15%
    System time(UTC) : 27 October 2017 15:46:24
    Broadcast Message : not set
HW:
   Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.1
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:49:e3
Satellite (DVB) : 00:20:0e:10:49:e3
# arp show
  NetAddr
             State MacAddr
   10.213.64.2 Dynamic e8:9a:8f:b7:bd:4a 1
#
C:\Documents and Settings\Administrator.DVB-RCS>ping -t 10.213.64.1
Pinging 10.213.64.1 with 32 bytes of data:
Reply from 10.213.64.1: bytes=32 time=528ms TTL=56
Reply from 10.213.64.1: bytes=32 time=548ms TTL=56
Reply from 10.213.64.1: bytes=32 time=549ms TTL=56
```

```
Reply from 10.213.64.1: bytes=32 time=539ms TTL=56
Reply from 10.213.64.1: bytes=32 time=551ms TTL=56
Reply from 10.213.64.1: bytes=32 time=524ms TTL=56
Reply from 10.213.64.1: bytes=32 time=521ms TTL=56
Reply from 10.213.64.1: bytes=32 time=539ms TTL=56
Reply from 10.213.64.1: bytes=32 time=539ms TTL=56
Reply from 10.213.64.1: bytes=32 time=545ms TTL=56
Reply from 10.213.64.1: bytes=32 time=535ms TTL=56
Reply from 10.213.64.1: bytes=32 time=522ms TTL=56

Ping statistics for 10.213.64.1:

Packets: Sent = 11, Received = 11, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:

Minimum = 521ms, Maximum = 551ms, Average = 536ms
```

Lista de sites acessados:

www.globo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.mg.gov.br - ok

Responsável pelo teste de navegação: Nome: Franciele Pereira de Sousa Função: Vice Diretora Rg- MG 19446559