


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior Operadora/Cliente: Ronaldo Candido

GRE/Prodemge: João Antinossi Responsável/cliente: Judite Leandro dos Santos Silva

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-CORO-220152MbpsVSAT



PRTG Traffic Grapher V6.2.0.907 - 9/10/2017 16:09:36

Satellite (DVB) TX Configuration

Auto start : Enabled

IDU Output Power : -20 dBm

IDU Max Output Power: 0.0 dBm

ODU Output Power : 32.7 dBm

EIRP : 46.0 dBW

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : None

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2)
IDU Output Power : -20.9 dBm
ODU Output Power : 33.1 dBm
EIRP : 46.4 dBW
Es/No : 14.0 dB

Header Compression : Disabled - HC for RCS2 not supported by HUB

Timing correction : -396 us (281736 us)

Frequency correction: 160 Hz

```
# dvb rx show
Satellite (DVB) RX Configuration
_____
Auto start
                     : Enabled
Auto start

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute
Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName
                                                                                 Name
Enable
          4.883300 12.176420 DVB-S2 104 0 0.0 E
* 0 0
Yes
Satellite (DVB) Receiver Status
            : On
: Forward link up
: 65281, Prodemge@Vodanet
: 12.176159 GHz
: 4.882972 Manage
-----
Rx State
DVB State
Network
Frequency
Symbol Rate
S2 ModCod
     - receiving : 4 QPSK-1/2
- current max : 21 16APSK-5/6
              : On
Pilot
Frame length : Short DVB S2 Mode : ACM
DVB S2 Stream type : MPEG-TS
Roll off : 0.20
SNR
                   : 15.1 dB
                   : -32 dBm
Input Power
# device show
System Information:
           : SEE-CORO-22015
   Name
    Location
                       : STEL-
    Contact
   System Up time : 0 days, 00:02:33 CPU Load : 6%
    System time(UTC) : 09 October 2017 15:14:24
    Broadcast Message : not set
HW:
    Model
                       : SatLink 2000
    HW ID
                       : 120033
    Main board ID
                       : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:5f:c6
Satellite (DVB) : 00:20:0e:10:5f:c6
Disparando 10.148.0.46 com 32 bytes de dados:
Resposta de 10.148.0.46: bytes=32 tempo=583ms TTL=57
Resposta de 10.148.0.46: bytes=32 tempo=560ms TTL=57
Resposta de 10.148.0.46: bytes=32 tempo=591ms TTL=57
Resposta de 10.148.0.46: bytes=32 tempo=569ms TTL=57
Resposta de 10.148.0.46: bytes=32 tempo=548ms TTL=57
Resposta de 10.148.0.46: bytes=32 tempo=572ms TTL=57
Resposta de 10.148.0.46: bytes=32 tempo=569ms TTL=57
Resposta de 10.148.0.46: bytes=32 tempo=626ms TTL=57
Resposta de 10.148.0.46: bytes=32 tempo=591ms TTL=57
Resposta de 10.148.0.46: bytes=32 tempo=567ms TTL=57
Estatísticas do Ping para 10.148.0.46:
   Pacotes: Enviados = 10, Recebidos = 10, Perdidos = 0 (0% de
Aproximar um número redondo de vezes em milissegundos:
   Mínimo = 548ms, Máximo = 626ms, Média = 577ms
```

ista de sites acessados:	
www.globo.com – ok	
www.hotmail.com – ok	
<u>www.google.com</u> – ok www.educacao.mg.gov.br – ok	
Responsável pelo teste de navegação: Nome: Leandro dos Santos Silva Função: Judite Leandro dos Santos Silva	
dentidade: 937470-3(MASP)	