


TERMO DE ACEITE TÉCNICO

Enable

Solicitante: PRODEMGE / SEE			
NOC/Operadora: Ermínio Junior		Operadora/Cliente Sidinei de Paula	
GRE/Prodemge: João Antinossi		Responsável/cliente Maynan Braz dos Santos	
Consórcio EMC/Vodanet	VSAT-ID SEE-CAIA-24279	Porta kbps 2Mbps	Plataforma VSAT





SatLink 2000

- Main board ID 120026, Revision R6.2
- SW ID 120208, Revision 16.0.1 Build 57

dvb tx show

Satellite (DVB) TX Configuration

Auto start : Enabled IDU Output Power : -20 dBm IDU Max Output Power: 0.0 dBm Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2) IDU Output Power : -20.2 dBm

Es/No : 15.5 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction: -713 us (260637 us)

Frequency correction: 140 Hz

dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName
* 0 0 13.333333 12.173500 DVB-S2 104 0 0.0 E Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.173588 GHz Symbol Rate : 13.332840 Msps

S2 ModCod

- receiving : 18 16APSK-2/3 - current max : 21 16APSK-5/6

Pilot: On
Frame length: Short
DVB S2 Mode: ACM
DVB S2 Stream type: MPEG-TS

Roll off : 0.20 SNR : 13.9 dB Input Power : -36 dBm

arp show

NetAddr State MacAddr If 10.215.0.2 Dynamic 00:e0:91:4d:f1:b8 1

device show System Information:

> Name : SEE-CAIA-24279 Location : Carmésia - MG

Contact :

System Up time : 0 days, 00:35:56

CPU Load : 42%

System time(UTC) : 06 March 2018 17:24:55

Broadcast Message : not set

HW:

Model : SatLink 2000 HW ID : 120033 Main board ID : 120026 R6.2

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:94:e1 Satellite (DVB) : 00:20:0e:10:94:e1

Pinging 10.215.0.1 with 32 bytes of data:

Reply from 10.215.0.1: bytes=32 time=559ms TTL=56 Reply from 10.215.0.1: bytes=32 time=561ms TTL=56 Reply from 10.215.0.1: bytes=32 time=525ms TTL=56 Reply from 10.215.0.1: bytes=32 time=519ms TTL=56 Reply from 10.215.0.1: bytes=32 time=525ms TTL=56 Reply from 10.215.0.1: bytes=32 time=528ms TTL=56 Reply from 10.215.0.1: bytes=32 time=535ms TTL=56 Reply from 10.215.0.1: bytes=32 time=535ms TTL=56 Reply from 10.215.0.1: bytes=32 time=531ms TTL=56 Reply from 10.215.0.1: bytes=32 time=516ms TTL=56 Reply from 10.215.0.1: bytes=32 time=530ms TTL=56 Reply from 10.215.0.1: bytes=32 time=546ms TTL=56 Reply from 10.215.0.1: bytes=32 time=577ms TTL=56 Reply from 10.215.0.1: bytes=32 time=513ms TTL=56 Reply from 10.215.0.1: bytes=32 time=548ms TTL=56 Reply from 10.215.0.1: bytes=32 time=778ms TTL=56

Ping statistics for 10.215.0.1:

Packets: Sent = 16, Received = 16, Lost = 0 (0% loss), Approximate round trip times in milli-seconds:

Minimum = 513ms, Maximum = 778ms, Average = 551ms

Resp: Maynan Braz dos Santos

Cargo:Professora Masp:1065163-6 www.hotmail.com

www.google.com

www.prodemge.gov.br

www.globo.com

www.youtube.com