

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior Operadora/Cliente: Ederson Martins

Responsável/cliente : ANTÔNIO BATISTA DE GRE/Prodemge: João Antinossi

FIGUEIREDO

Consórcio **VSAT-ID** Porta kbps **Plataforma** 2Mbps EMC/Vodanet **VSAT** SEE-MIAS-22043



PRTG Traffic Grapher V6.2.0.907 - 14/10/2017 21:41:39

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E Yes 1 1 16.667000 11.962753 DVB-S2 2 0.0 E Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

: 65281, Prodemge@Vodanet Network

Frequency : 12.176284 GHz Symbol Rate : 4.883009 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max: 16 8PSK-8/9

Pilot : On : Short Frame length DVB S2 Mode : ACM DVB S2 Stream type: MPEG-TS

```
: 0.20
Roll off
SNR
           : 14.4 dB
Input Power : -29 dBm
Satellite (DVB) TX Configuration
Auto start
             : Enabled
IDU Output Power : -21 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.5 dBm
EIRP
           : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode
               : VC-Mux
Header Compression: UDP/IP
Satellite (DVB) Transmitter Status
State
           : On (DVB-RCS2)
IDU Output Power : -16.9 dBm
ODU Output Power : 33.3 dBm
EIRP
           : 46.3 dBW
Es/No
           : 14.0 dB
Header Compression: Disabled - HC for RCS2 not supported by HUB
Timing correction: -198 us (280985 us)
Frequency correction: 110 Hz
System Information:
 Name : SEE-MIAS-22043
 Location : MINAS NOVAS/MG
Contact :
 System Up time : 0 days, 00:15:19
 CPU Load : 16%
 System time(UTC) : 14 October 2017 20:30:07
  Broadcast Message : not set
HW:
             : SatLink 2000
 Model
 HW ID
             : 120033
  Main board ID : 120026 R6.2
MAC addresses:
 Ethernet (LAN) : 00:20:0e:10:56:0b
 Satellite (DVB) : 00:20:0e:10:56:0b
# arp show
 NetAddr State MacAddr
 10.212.115.2 Dynamic 48:ee:0c:c3:3e:39 1
```

Pinging 10.212.115.1 with 32 bytes of data:

Reply from 10.212.115.1: bytes=32 time=625ms TTL=56 Reply from 10.212.115.1: bytes=32 time=577ms TTL=56 Reply from 10.212.115.1: bytes=32 time=603ms TTL=56 Reply from 10.212.115.1: bytes=32 time=563ms TTL=56 Reply from 10.212.115.1: bytes=32 time=633ms TTL=56 Reply from 10.212.115.1: bytes=32 time=635ms TTL=56 Reply from 10.212.115.1: bytes=32 time=612ms TTL=56 Reply from 10.212.115.1: bytes=32 time=564ms TTL=56 Reply from 10.212.115.1: bytes=32 time=567ms TTL=56 Reply from 10.212.115.1: bytes=32 time=635ms TTL=56 Reply from 10.212.115.1: bytes=32 time=635ms TTL=56 Reply from 10.212.115.1: bytes=32 time=570ms TTL=56

Ping statistics for 10.212.115.1:

Packets: Sent = 11, Received = 11, Lost = 0 (0% loss),

Approximate round trip times in milli-seconds:

Minimum = 555ms, Maximum = 635ms, Average = 591ms

Sites acessados

www.globo.com ok

www.yahoo.com.br- ok

www.hotmail.com- ok

<u>www.google.com</u> – ok

www.prodemge.gov.br - ok

Responsável: ANTÔNIO BATISTA DE FIGUEIREDO

CARGO:DIRETOR RG:MG-10.604.194 Horário: das 07 as 16:15

OBS: não possui computador no local apenas o notebook do professor