


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Walter Leandro

GRE/Prodemge: João Antinossi Responsável/cliente: Sueli de Fatima Veloso

> Consórcio Porta kbps Plataforma **VSAT-ID** EMC/Vodanet **VSAT** SEE-COAS-23512 2Mbps



Satellite (DVB) RX Configuration -----

Auto start : Enabled

: 23 16APSK-9/10 Max Traffic MODCOD

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 8.883000 12.176420 DVB-S2 104 0 0.0 E

Yes

4.883300 12.176420 DVB-S2 2 0 0.0 E 1 1

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

: 03201, -: 12.176438 GHz : 8.882880 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 22 16APSK-8/9 - current max : 22 16APSK-8/9

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.6 dB Input Power : -36 dBm

```
Satellite (DVB) TX Configuration
_____
Auto start
                    : Enabled
Auto start : Enabled IDU Output Power : -17 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
: On (DVB-RCS2)

IDU Output Power : -17.1 dBm

Es/No
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -399 us (266354 us)
Frequency correction: 70 Hz
System Information:
   Name
                        : SEE-COAS-23512
    Location
                         : COUTO DE MAGALHÃES DE MINAS - MG
    Contact
    System Up time : 0 days, 00:05:32 CPU Load : 18%
    System time(UTC) : 27 December 2017 14:17:16 Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
                        : 120033
    HW ID
                        : 120026 R6.2
    Main board ID
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:94:a5
Satellite (DVB) : 00:20:0e:10:94:a5
NetAddr
             State MacAddr
   10.213.104.2 Dynamic c8:9c:dc:01:61:f3 1
Pinging 10.213.104.1 with 32 bytes of data:
Reply from 10.213.104.1: bytes=32 time=587ms TTL=56
Reply from 10.213.104.1: bytes=32 time=529ms TTL=56
Reply from 10.213.104.1: bytes=32 time=542ms TTL=56
Reply from 10.213.104.1: bytes=32 time=543ms TTL=56
Reply from 10.213.104.1: bytes=32 time=567ms TTL=56
Reply from 10.213.104.1: bytes=32 time=548ms TTL=56
Reply from 10.213.104.1: bytes=32 time=564ms TTL=56
Reply from 10.213.104.1: bytes=32 time=552ms TTL=56
Reply from 10.213.104.1: bytes=32 time=555ms TTL=56
Reply from 10.213.104.1: bytes=32 time=575ms TTL=56
Ping statistics for 10.213.104.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 529ms, Maximum = 587ms, Average = 556ms
```

Lista de sites acessados:
www.globo.com – ok
www.yahoo.com – ok
www.hotmail.com – ok
www.google.com – ok
www.educacao.mg.gov.br – ok
<u>www.prodemge.gov.br</u> – ok
Responsável pelo teste de navegação:
Nome: Sueli de Fatima Veloso
Função: Vice Diretora
MASP: 2767564
Telefone: 38-3533-1592
Funcionamento: 07:00hrs às 22:00hrs