


TERMO DE ACEITE TÉCNICO

Name

Solicitante: PRODEMGE / SEE NOC/Operadora: Ermínio Junior Operadora/Cliente Ronaldo Candido Responsável/cliente Nailson Eleutério GRE/Prodemge: João Antinossi Consórcio **VSAT-ID** Porta kbps **Plataforma EMC/Vodanet** SEE-BELO-22758 2Mbps **VSAT**





SatLink 2000

- Main board ID 120026, Revision R6.2
- SW ID 120208, Revision 16.0.1 Build 57

dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

: 15 minute RX watchdog

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E Yes 11.962753 DVB-S2 2 0 0.0 E Yes 1 1 16.667000

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

: 65281, Prodemge@Vodanet Network

: 12.176674 GHz Frequency Symbol Rate : 4.883026 Msps

S2 ModCod

- receiving : 20 16APSK-4/5 - current max : 21 16APSK-5/6

Pilot Frame length : Short DVB S2 Mode : ACM

```
DVB S2 Stream type: MPEG-TS
Roll off
            : 0.20
SNR
             : 15.6 dB
Input Power
               : -36 dBm
# dvb tx show
Satellite (DVB) TX Configuration
          : Enabled
Auto start
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
            : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode
                : VC-Mux
Header Compression: UDP/IP
Satellite (DVB) Transmitter Status
            : On (DVB-RCS2)
IDU Output Power : -20.6 dBm
ODU Output Power : 33.3 dBm
             : 46.6 dBW
Es/No
             : 13.5 dB
Header Compression: Disabled - HC for RCS2 not supported by HUB
Timing correction : -452 us (281581 us)
Frequency correction: 40 Hz
# arp show
 NetAddr
             State MacAddr
  10.214.64.2 Dynamic 80:ee:73:a4:e2:ba 1
# device show
System Information:
               : SEE-BELO-22758
  Name
  Location
                : Berilo - MG
  Contact
  System Up time
                   : 0 days, 00:17:11
  CPU Load
                 : 16%
  System time(UTC) : 13 November 2017 13:11:45
  Broadcast Message : not set
HW:
  Model
                : SatLink 2000
  HW ID
                : 120033
  Main board ID
                  : 120026 R6.2
MAC addresses:
  Ethernet (LAN)
                   : 00:20:0e:10:59:10
```

Satellite (DVB) : 00:20:0e:10:59:10

Pinging 10.214.64.1 with 32 bytes of data:

Reply from 10.214.64.1: bytes=32 time=505ms TTL=56 Reply from 10.214.64.1: bytes=32 time=555ms TTL=56 Reply from 10.214.64.1: bytes=32 time=599ms TTL=56 Reply from 10.214.64.1: bytes=32 time=572ms TTL=56 Reply from 10.214.64.1: bytes=32 time=536ms TTL=56 Reply from 10.214.64.1: bytes=32 time=508ms TTL=56 Reply from 10.214.64.1: bytes=32 time=557ms TTL=56 Reply from 10.214.64.1: bytes=32 time=537ms TTL=56 Reply from 10.214.64.1: bytes=32 time=535ms TTL=56 Reply from 10.214.64.1: bytes=32 time=569ms TTL=56

Ping statistics for 10.214.64.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),

Approximate round trip times in milli-seconds:

Minimum = 505ms, Maximum = 599 ms, Average = 567ms

www.hotmail.com

www.google.com

www.prodemge.gov.br

Responsável	Nailson Eleutério
Cargo	Diretor
Identidade	638.691-6
Telefone	038-9-9992-4151
Funcionamento	06:00-22:00