

TERMO DE ACEITE TÉCNICO

Solicitante: VIVO- Projeto Escolas Rurais

NOC/Operador: Rogério Momi Frias Cliente: VIVO

EmpresaVSAT-IDLink kbpsPlataformaEMC BrasilVIVO-PER-25018922-PB256/128VSAT



Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

ldx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable

* 0 0 9.320000 12.055825 DVB-S2 102 0 0.0 E Yes

Satellite (DVB) Receiver Status

_ _ _

Rx State : On

DVB State : Forward link up
Network : 1326, T14R Beam
Frequency : 12.055832 GHz
Symbol Rate : 9.319981 Msps

S2 ModCod

- receiving : 13 8PSK-2/3 - current max : 16 8PSK-8/9

Pilot : On Frame length : Short DVB S2 Mode : ACM

DVB S2 Stream type: MPEG-TS

Roll off : 0.20 SNR : 13.4 dB Input Power : -25 dBm

Satellite (DVB) TX Configuration

Auto start : Enabled IDU Output Power : -30 dBm IDU Max Output Power: 0.0 dBm ODU Output Power : 33.2 dBm

EIRP : 46.5 dBW

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : None

Satellite (DVB) Transmitter Status

State : On (DVB-RCS) IDU Output Power : -21.8 dBm ODU Output Power : 32.7 dBm

EIRP : 46.0 dBW Es/No : 16.0 dB

Header Compression: Disabled

Timing correction : -194 us (261250 us)

Frequency correction: -120 Hz

```
Aircrasoft Vindows [versão 6.1.7681]
Copyright (c) 2899 Microsoft Corporation. Todos es direitos reservados.

C:\Users\Vidar\ping 8.8.8.8 -t

Disparando 8.8.8.8 com 32 bytes de dados:
Respost de 8.8.8.8: bytes=32 tenpo=673ms IIL=55
Respost de 8.8.8.8: bytes=32 tenpo=71ms IIL=55
Respost de 8.8.8.8: bytes=32 tenpo=518ms IIL=55
Respost de 8.8.8.8: bytes=32 tenpo=518ms IIL=55
Respost de 8.8.8.8: bytes=32 tenpo=61ms IIL=55
Respost de 8.8.8.8: bytes=32 tenpo=651ms IIL=55
Respost de 8.8.8.8: bytes=32 tenpo=671ms IIL=55
Respost de 8.8.8.8: bytes=32 tenpo=671ms IIL=55
Respost de 8.8.8.8: bytes=32 tenpo=671ms IIL=55
Respost de 8.8.8.8: bytes=32 tenpo=697ms III-55
Respost de 8.8.8.8: bytes=32 tenpo=697ms
```