


## TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Jean Polini

Responsável/cliente: JORGE DA SILVA MELO GRE/Prodemge: João Antinossi

> Consórcio Porta kbps Plataforma **VSAT-ID** EMC/Vodanet SEE-MACU-23676 2Mbps **VSAT**





Satellite (DVB) RX Configuration Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

\* 0 0 8.883000 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 0 0.0 E 12.176420 DVB-S2 2 4.883300

Yes

Satellite (DVB) Receiver Status

\_\_\_\_\_

Rx State : On

: Forward link up DVB State

: 65281, Prodemge@Vodanet : 12.176432 GHz Network

Frequency : 8.883193 Msps Symbol Rate

S2 ModCod

- receiving : 22 16APSK-8/9 - current max : 22 16APSK-8/9

: On Pilot Frame length : Short : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.6 dB : -40 dBm Input Power

```
Satellite (DVB) TX Configuration
_____
                    : Enabled
Auto start
Auto start : Enabled IDU Output Power : -18 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
: On (DVB-RCS2)

IDU Output Power : -18.2 dBm

Es/No
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -213 us (266335 us)
Frequency correction: 170 Hz
System Information:
                     : SEE-MACU-23676
    Name
    Location
                         : Manhua u - MG
    Contact
    System Up time : 0 days, 00:34:11
CPU Load : 11%
System time(UTC) : 12 January 2018 19:53:17
Broadcast Message : not set
HW:
    Model
                         : SatLink 2000
                         : 120033
    HW ID
                        : 120026 R6.2
    Main board ID
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:7b:29
Satellite (DVB) : 00:20:0e:10:7b:29
NetAddr
           State MacAddr
    10.215.35.2 Dynamic 64:1c:67:62:2e:12 1
Pinging 10.215.35.1 with 32 bytes of data:
Reply from 10.215.35.1: bytes=32 time=556ms TTL=56
Reply from 10.215.35.1: bytes=32 time=564ms TTL=56
Reply from 10.215.35.1: bytes=32 time=648ms TTL=56
Reply from 10.215.35.1: bytes=32 time=526ms TTL=56
Reply from 10.215.35.1: bytes=32 time=625ms TTL=56
Reply from 10.215.35.1: bytes=32 time=551ms TTL=56
Reply from 10.215.35.1: bytes=32 time=531ms TTL=56
Reply from 10.215.35.1: bytes=32 time=530ms TTL=56
Reply from 10.215.35.1: bytes=32 time=551ms TTL=56
Reply from 10.215.35.1: bytes=32 time=535ms TTL=56
Ping statistics for 10.215.35.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 526ms, Maximum = 648ms, Average = 561ms
```

Lista de sites acessados:  www.globo.com – ok	
<u>www.yahoo.com</u> – ok	
www.hotmail.com – ok	
www.google.com – ok	
www.educacao.mg.gov.br – ok	
www.prodemge.gov.br – ok	
Responsável pelo teste de navegação:	
Nome: JORGE DA SILVA MELO	
Função: SECRETARIO	
MASP: 1292458-5	
Telefone: 33 999248663	
Horário: 07:00 as 17:45	