

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Hernan Alves Operadora/Cliente: Jean Polini

GRE/Prodemge: João Antinossi Responsável/cliente: Alucelia Mendes Oliveira Ribeiro

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-BOAS-221042MbpsVSAT

Port eth0 on SEE-BOAS-22104 (10.212.157.1)



```
# dvb rx show
```

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes d

Satellite (DVB) Receiver Status

Rx State : On

DVB State : vForward link up

Network: 65281, Prodemge@Vodanet

Frequency: 12.176370 GHz Symbol Rate: 4.882974 Msps

S2 ModCod

- receiving : 19 16APSK-3/4 - current max : 21 16APSK-5/6

Pilot : On

Frame length : Short DVB S2 Mode : ACM

DVB S2 Stream type : MPEG-TS

Roll off : 0.20

```
SNR : 14.9 dB
Input Power: -36 dBm
dvb tx show
Satellite (DVB) TX Configuration
_____
Auto start : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power: 33.2 dBm
EIRP: 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
______
State : On (DVB-RCS2)
IDU Output Power : -18.8 dBm
ODU Output Power: 33.4 dBm
EIRP: 46.7 dBW
Es/No : 8.0 dB
Header Compression: Disabled - HC for RCS2 not supported by HUB
Timing correction: -284 us (281358 us)
Frequency correction: 80 Hz
# device show
System Information:
Name : SEE-ALAS-22104
Location: BONITO DE MINAS - MG
Contact :
System Up time: 2 days, 20:42:02
CPU Load : 15%
System time(UTC): 16 November 2017 20:01:55
Broadcast Message : not set
HW:
Model: SatLink 2000
HW ID : 120033
Main board ID : 120026 R6.2
MAC addresses:
Ethernet (LAN): 00:20:0e:10:53:bb
Satellite (DVB) : 00:20:0e:10:53:bb
Pinging 10.212.157.1 with 32 bytes of data:
Reply from 10.212.157.1: bytes=32 time=552ms TTL=56
Reply from 10.212.157.1: bytes=32 time=535ms TTL=56
Reply from 10.212.157.1: bytes=32 time=536ms TTL=56
Reply from 10.212.157.1: bytes=32 time=544ms TTL=56
Reply from 10.212.157.1: bytes=32 time=528ms TTL=56
Reply from 10.212.157.1: bytes=32 time=521ms TTL=56
Reply from 10.212.157.1: bytes=32 time=577ms TTL=56
Reply from 10.212.157.1: bytes=32 time=555ms TTL=56
Reply from 10.212.157.1: bytes=32 time=542ms TTL=56
Reply from 10.212.157.1: bytes=32 time=534ms TTL=56
Ping statistics for 10.212.157.1:
Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
Minimum = 521ms, Maximum = 577ms, Average = 542ms
```

Time de standardos
Lista de sites acessados:
www.globo.com – ok
www.yahoo.com – ok
www.hotmail.com - ok
<u>www.google.com</u> – ok
www.educacao.mg.gov.br – ok
<u>www.prodemge.gov.br</u> – ok
Responsável pelo teste de navegação:
Nome: Edvilma de Barros Bizerra
Função: Diretora
MASP: 935 921-7
Contato: 38 999373003
Horário de funcionamento: