


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Joao Gustavo

GRE/Prodemge: João Antinossi Responsável/cliente: Gleide Aparecida Cardoso Oliveira

> Consórcio **VSAT-ID** Porta kbps **Plataforma** EMC/Vodanet SEE-SAAS-22787 2Mbps **VSAT**



Satellite (DVB) RX Configuration \_\_\_\_\_ Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

12.176420 DVB-S2 104 \* 0 0 4.883300 0 0.0 E

Yes

1 16.667000 11.962753 DVB-S2 2 0.0 E 1

Yes

Satellite (DVB) Receiver Status \_\_\_\_\_

Rx State : On

DVB State

Network

: Forward link up : 65281, Prodemge@Vodanet : 12.176420 GHz Frequency Symbol Rate : 4.883033 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 16APSK-5/6 - current max : 21

Pilot : On Frame length : Short
DVB S2 Mode : ACM DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.3 dB : -35 dBm Input Power

```
Satellite (DVB) TX Configuration
_____
Auto start
                   : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : max
EIRP
                   : max
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
                    : On (DVB-RCS2)
State
IDU Output Power : -13.6 dBm
ODU Output Power : 34.6 dBm
EIRP
                    : 47.9 dBW
Es/No
                    : 14.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{: Disabled} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -223 us (280652 us)
Frequency correction: 80 Hz
System Information:
   Name
                       : SEE-SAAS-22787
    Location
                        : SALINAS - MG
    Contact
   System Up time : 0 days, 00:06:55 CPU Load : 6%
                       : 18 November 2017 18:55:13
    System time(UTC)
    Broadcast Message : not set
HW:
   Model
                       : SatLink 2000
                       : 120033
    HW ID
    Main board ID
                       : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:4c:45
Satellite (DVB) : 00:20:0e:10:4c:45
NetAddr
          State MacAddr
   10.214.101.2 Dynamic b4:99:ba:00:92:6b 1
Pinging 10.214.101.1 with 32 bytes of data:
Reply from 10.214.101.1: bytes=32 time=550ms TTL=56
Reply from 10.214.101.1: bytes=32 time=572ms TTL=56
Reply from 10.214.101.1: bytes=32 time=571ms TTL=56
Reply from 10.214.101.1: bytes=32 time=608ms TTL=56
Reply from 10.214.101.1: bytes=32 time=549ms TTL=56
Reply from 10.214.101.1: bytes=32 time=585ms TTL=56
Reply from 10.214.101.1: bytes=32 time=556ms TTL=56
Reply from 10.214.101.1: bytes=32 time=565ms TTL=56
Reply from 10.214.101.1: bytes=32 time=595ms TTL=56
Reply from 10.214.101.1: bytes=32 time=543ms TTL=56
Ping statistics for 10.214.101.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 543ms, Maximum = 608ms, Average = 569ms
```

## Lista de sites acessados: www.globo.com – ok www.yahoo.com – ok <u>www.hotmail.com</u> – ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: Gleide Aparecida Cardoso Oliveira Função: Diretora MASP: 867992-0 Telefone: 38-99938-4973 Funcionamento: 07:00 as 21:30