

# TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Rodrigo Alves

GRE/Prodemge: João Antinossi Responsável/cliente: Grasiela Bonfin Andrade de Souza

> Plataforma Consórcio **VSAT-ID** Porta kbps **VSAT** EMC/Vodanet SEE-PAIS-23353 2Mbps

#### Port eth0 on SEE-PAIS-23353 (10.214.7.1)



## Satellite (DVB) RX Configuration \_\_\_\_\_

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

\* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

0.000000 0.000000 DVB-S2 2 0 0.0 E 1 1

Yes

### Satellite (DVB) Receiver Status \_\_\_\_\_\_

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

: 65281, Proder : 12.176515 GHz Frequency Symbol Rate : 4.883022 Msps

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On Frame length DVB S2 Mode : Short : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.5 dB Input Power : -39 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
______
State : On (DVB-RCS2)
IDU Output Power : -14.1 dBm
ODU Output Power : 32.1 dBm
EIRP
                    : 45.4 dBW
Es/No
                    : 13.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -439 us (281374 us)
Frequency correction: 20 Hz
System Information:
    Name
                        : SEE-PAIS-23353
    Location
                        : PATIS - MG
    Contact
    System Up time : 0 days, 00:01:37 CPU Load : 15%
    System time(UTC) : 06 December 2017 14:08:30
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
    conernet (LAN) : 00:20:0e:10:5c:b7
Satellite (DVB) : 00:20:00:10:5c
MAC addresses:
NetAddr
            State MacAddr
     10.214.7.2 Dynamic 2c:27:d7:a0:cd:ed 1
Pinging 10.214.7.1 with 32 bytes of data:
Reply from 10.214.7.1: bytes=32 time=536ms TTL=56
Reply from 10.214.7.1: bytes=32 time=562ms TTL=56
Reply from 10.214.7.1: bytes=32 time=601ms TTL=56
Reply from 10.214.7.1: bytes=32 time=525ms TTL=56
Reply from 10.214.7.1: bytes=32 time=565ms TTL=56
Reply from 10.214.7.1: bytes=32 time=577ms TTL=56
Reply from 10.214.7.1: bytes=32 time=567ms TTL=56
Reply from 10.214.7.1: bytes=32 time=546ms TTL=56
Reply from 10.214.7.1: bytes=32 time=625ms TTL=56
Reply from 10.214.7.1: bytes=32 time=532ms TTL=56
Ping statistics for 10.214.7.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 525ms, Maximum = 625ms, Average = 563ms
```

# Lista de sites acessados: <u>www.globo.com</u> – ok www.yahoo.com - ok <u>www.hotmail.com</u> – ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: Grasiela Bonfin Andrade de Souza Função: Diretora MASP: 5973839 Telefone: 38-32398153 Funcionamento: 07:00h às 22:00h