

TERMO DE ACEITE TÉCNICO

18:55


18:56

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Ederson Martins

GRE/Prodemge: João Antinossi Responsável/cliente: Rossini Ornelas Esteves

> Consórcio **VSAT-ID** Porta kbps Plataforma EMC/Vodanet SEE-ARAI-22753 2Mbps **VSAT**



Satellite (DVB) RX Configuration _____

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

18:53

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Bandwidth Traffic IN Bandwidth Traffic OUT

Enable

100

18:52

* 0 0 12.176420 DVB-S2 104 0 0.0 E 4.883300

Yes

16.667000 11.962753 DVB-S2 2 0 0.0 E 1 1

Yes

Satellite (DVB) Receiver Status ______

Rx State : On

DVB State : Forward link up

: 65281, Prodemge@Vodanet Network

: 65281, Proder : 12.176503 GHz Frequency Symbol Rate : 4.882992 Msps

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.2 dB Input Power : -28 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -19.5 dBm
ODU Output Power : 32.4 dBm
EIRP
                    : 45.7 dBW
Es/No
                    : 13.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -334 us (280754 us)
Frequency correction: 100 Hz
System Information:
    Name
                        : SEE-ARAI-22753
    Location
                        : ARAÇUAÍ - MG
    Contact
    System Up time : 0 days, 00:11:51 CPU Load : 13%
    System time (UTC) : 16 November 2017 14:09:59
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:5b:91
Satellite (DVB) : 00:20:0e:10:5b:91
    Ethernet (LAN)
NetAddr
           State MacAddr
    10.214.59.2 Dynamic 1c:39:47:5b:e2:48 1
Pinging 10.214.59.1 with 32 bytes of data:
Reply from 10.214.59.1: bytes=32 time=547ms TTL=56
Reply from 10.214.59.1: bytes=32 time=546ms TTL=56
Reply from 10.214.59.1: bytes=32 time=560ms TTL=56
Reply from 10.214.59.1: bytes=32 time=608ms TTL=56
Reply from 10.214.59.1: bytes=32 time=537ms TTL=56
Reply from 10.214.59.1: bytes=32 time=953ms TTL=56
Reply from 10.214.59.1: bytes=32 time=541ms TTL=56
Reply from 10.214.59.1: bytes=32 time=560ms TTL=56
Reply from 10.214.59.1: bytes=32 time=550ms TTL=56
Reply from 10.214.59.1: bytes=32 time=552ms TTL=56
Ping statistics for 10.214.59.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 537ms, Maximum = 953ms, Average = 595ms
```

Lista de sites acessados: <u>www.globo.com</u> – ok www.yahoo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: Rossini Ornelas Esteves Função: Diretor MASP: 1113834-4 Telefone: 33-99965-2119 Funcionamento: 07:00 às 17:00h