


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Eduardo Tadra

GRE/Prodemge: João Antinossi Responsável/cliente: Ilma Martins de Moraes

> Porta kbps Consórcio **VSAT-ID** Plataforma EMC/Vodanet SEE-TENI-22984 2Mbps **VSAT**



Satellite (DVB) RX Configuration _____

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

: 15 minute RX watchdog

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

12.176420 DVB-S2 104 0 0.0 E 4.883300 * 0 0

Yes

11.962753 DVB-S2 2 0 0.0 E 1 1 16.667000

Yes

Satellite (DVB) Receiver Status

Rx State : On

: Forward link up DVB State

: 65281, Prodemge@Vodanet Network

: 65281, Prodei : 12.176197 GHz Frequency Symbol Rate : 4.883006 Msps

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS : 0.20 Roll off : 15.9 dB SNR Input Power : -28 dBm

```
Satellite (DVB) TX Configuration
_____
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
                    : 46.5 dBW
EIRP
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
: On (DVB-RCS2)

IDU Output Power : -19.0 dBm

ODU Output Power : 33.1 dBm

EIRP
______
Es/No
                    : 14.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -308 us (280479 us)
Frequency correction: 110 Hz
System Information:
    Name
                        : SEE-TENI-22984
    Location
                        : Teófilo Otoni - MG
    Contact
    System Up time : 0 days, 00:35:06 CPU Load : 16%
    System time(UTC) : 29 November 2017 14:16:37
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:54:52
Satellite (DVB) : 00:20:0e:10:54:52
    Ethernet (LAN)
NetAddr
          State MacAddr
   10.215.184.2 Dynamic b8:70:f4:6e:b3:ab 1
Pinging 10.215.184.1 with 32 bytes of data:
Reply from 10.215.184.1: bytes=32 time=519ms TTL=56
Reply from 10.215.184.1: bytes=32 time=585ms TTL=56
Reply from 10.215.184.1: bytes=32 time=527ms TTL=56
Reply from 10.215.184.1: bytes=32 time=561ms TTL=56
Reply from 10.215.184.1: bytes=32 time=541ms TTL=56
Reply from 10.215.184.1: bytes=32 time=548ms TTL=56
Reply from 10.215.184.1: bytes=32 time=530ms TTL=56
Reply from 10.215.184.1: bytes=32 time=554ms TTL=56
Reply from 10.215.184.1: bytes=32 time=529ms TTL=56
Reply from 10.215.184.1: bytes=32 time=534ms TTL=56
Ping statistics for 10.215.184.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 519ms, Maximum = 585ms, Average = 542ms
```

Lista de sites acessados: www.globo.com - ok www.yahoo.com - ok www.hotmail.com - ok www.google.com - ok www.google.com - ok

www.prodemge.gov.br – ok

Responsável pelo teste de navegação:

Nome: Ilma Martins de Moraes

Função: Diretora MASP: 635220-7 Telefone: 33-35286015

Funcionamento: 07:00h às 16:30h