

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Paulo de Tarso Operadora/Cliente: Ederson Martins

GRE/Prodemge: João Antinossi Responsável/cliente: Soraya Jamel

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-SAES-222642048/1024VSAT

Port eth0 on SEE-SAES-22264 (10.213.63.1)



PRTG Traffic Grapher V6.2.0.907 - 10/27/2017 9:09:47 PM

dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

```
DVB State
                    : Forward link up
                 : 65281, Prodemge@Vodanet
: 12.176398 GHz
Frequency
Symbol Rate
                    : 4.882997 Msps
S2 ModCod
   - receiving : 14 8PSK-3/4
     - current max : 21 16APSK-5/6
Pilot : On
Frame length : Short
DVB S2 Mode : ACM
DVB S2 Stream type : MPEG-TS
Roll off : 0.20
SNR : 15.5 dB
Input Power : -34 dBm
Input Power
                    : -34 dBm
# dvb tx show
Satellite (DVB) TX Configuration
-----
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                     : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
State : On (DVB-RCS2)
IDU Output Power : -16.5 dBm
ODU Output Power : 33.1 dBm
EIRP
Es/No
                    : 46.4 dBW
                    : 14.5 dB
Header Compression : Disabled - HC for RCS2 not supported by HUB
Timing correction : -230 us (281202 us)
Frequency correction: 100 Hz
# device show
System Information:
          : SEE-SAES-22264
:ion : SÃO JOÃO DAS M:
ct :
   Name
    Location
                        : SÃO JOÃO DAS MISSÕES - MG
    Contact
    System Up time : 0 days, 00:58:43
CPU Load : 10%
System time(UTC) : 27 October 2017 20:47:01
    Broadcast Message : not set
HW:
                         : SatLink 2000
                         : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:54:a7
Satellite (DVB) : 00:20:0e:10:54:a7
# arp show
   NetAddr
             State MacAddr
   10.213.63.2 Dynamic e8:9a:8f:b7:bd:4a 1
Pinging 10.213.63.1 with 32 bytes of data:
Reply from 10.213.63.1: bytes=32 time=667ms TTL=56
Reply from 10.213.63.1: bytes=32 time=573ms TTL=56
Reply from 10.213.63.1: bytes=32 time=548ms TTL=56
```

```
Reply from 10.213.63.1: bytes=32 time=537ms TTL=56
Reply from 10.213.63.1: bytes=32 time=573ms TTL=56
Reply from 10.213.63.1: bytes=32 time=561ms TTL=56
Reply from 10.213.63.1: bytes=32 time=550ms TTL=56
Reply from 10.213.63.1: bytes=32 time=539ms TTL=56
Reply from 10.213.63.1: bytes=32 time=530ms TTL=56
Reply from 10.213.63.1: bytes=32 time=530ms TTL=56
Reply from 10.213.63.1: bytes=32 time=534ms TTL=56

Ping statistics for 10.213.63.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 530ms, Maximum = 667ms, Average = 561ms
```

Lista de sites acessados:

www.globo.com - ok www.yahoo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok

Nome do resp- Romaria Gonçalve de Souza Tel - 38 -9 9902-1995 Cargo- Vice diretora Masp- 1243568-1 Tec - Gilvan P de Brito Júnior Tel- 11 9 8901-8103