

TERMO DE ACEITE TÉCNICO

Solicitante: VIVO- Projeto Escolas Rurais

NOC/Operador: Allan Santos Cliente: VIVO

 Empresa
 VSAT-ID
 Link kbps
 Plataforma

 EMC Brasil
 VIVO-PER-31189448-MG
 256/128
 VSAT



```
10.53.0.91 - PuTTY
# dvb tx show
Satellite (DVB) TX Configuration
Auto start : Enabled IDU Output Power : -30 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.7 dBm EIRP : 47.0 dBW
Default CW Frequency: 0.000000 GHz
ATM mode
                     : VC-Mux
Header Compression : None
Satellite (DVB) Transmitter Status
State : On (TDMA)
IDU Output Power : -21.9 dBm
ODU Output Power : 33.9 dBm
                     : 47.2 dBW
EIRP
Es/No
                     : 14.0 dB
Header Compression : Disabled
Timing correction : -142 us (261813 us)
Frequency correction: -220 Hz
@ 10.53.0.91 - PuTTY
```

dvb rx show Satellite (DVB) RX Configuration ______ Auto start : Enabled : Max MODCOD : 23 16APSK-9/10 (SNR threshold: 23.5 dB) : 15 minute RX watchdog Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId Enable * 0 0 9.320000 12.055825 DVB-S2 4 Yes 0.000000 DVB-S2 2 0.000000 Yes Satellite (DVB) Receiver Status : On : Forward link up Rx State DVB State Network : 1326, GlobalIP@Telstar-14R : 12.055653 GHz : 9.319949 Msps Frequency Symbol Rate 52 ModCod - receiving : 1 QPSK-1/4 - current max : 23 16APSK-9/10 : On Frame length : Short DVB S2 Mode : ACM Roll off : 0.25 : 13.6 dB Input Power : -26 dBm

Ping desde o MGMT- Server ao IP de trafego e para o DVB.

```
C:\Command Prompt

C:\Copyright 1985-2003 Microsoft Corp.

C:\Documents and Settings\Administrator.DUB-RCS\ping 10.53.0.91

Pinging 10.53.0.91 with 32 bytes of data:

Reply from 10.53.0.91: bytes=32 time=1236ms TTL=61

Reply from 10.53.0.91: bytes=32 time=823ms TTL=61

Reply from 10.53.0.91: bytes=32 time=645ms TTL=61

Reply from 10.53.0.91: bytes=32 time=566ms TTL=61

Ping statistics for 10.53.0.91:

Packets: Sent = 4, Received = 4, Lost = 0 (0x loss),
Approximate round trip times in milli-seconds:
Minimum = 566ms, Maximum = 1236ms, Average = 817ms

C:\Documents and Settings\Administrator.DUB-RCS\
C:\Documents and Settings\Administrator.DUB-RCS\ping 10.29.0.185

Pinging 10.29.0.185 with 32 bytes of data:

Reply from 10.29.0.185: bytes=32 time=604ms TTL=61

Reply from 10.29.0.185: bytes=32 time=650ms TTL=61

Reply from 10.29.0.185: bytes=32 time=650ms TTL=61

Ping statistics for 10.29.0.185:
Packets: Sent = 4, Received = 4, Lost = 0 (0x loss),
Approximate round trip times in milli-seconds:

Minimum = 587ms, Maximum = 650ms, Average = 622ms

C:\Documents and Settings\Administrator.DUB-RCS\_
```

Ping desde dentro da VSAT 8.8.8.8

```
10.53.0.91 - PuTTY
# device show
System Information:
   Name
                       : VIVO-PER-31189448-MG
   Location
                       : Pedra Azul - MG
   Contact
   System Up time : 0 days, 00:25:41
                       : 11%
   CPU Load
                       : 09 September 2015 15:54:30
    System time (UTC)
    Broadcast Message : not set
HW:
   Model
                       : SatLink 2000
   HW ID
                       : 120033
    Main board ID
                       : 120026 R6.2
MAC addresses:
                     : 00:20:0e:10:5d:94
: 00:20:0e:10:5d:94
    Ethernet (LAN)
    Satellite (DVB)
# ping 8.8.8.8
64 bytes from 8.8.8.8: time=700 ms
64 bytes from 8.8.8.8: time=870 ms
64 bytes from 8.8.8.8: time=710 ms
64 bytes from 8.8.8.8: time=650 ms
64 bytes from 8.8.8.8: time=650 ms
--- 8.8.8.8 ping statistics ---
5 packets transmitted, 5 received, 0.00 percent packet loss
rtt min/avg/max = 650/710/870 ms
```