

TERMO DE ACEITE TÉCNICO

Solicitante: VIVO- Projeto Escolas Rurais

Cliente: VIVO NOC/Operador: Rogério Momi Frias

> **Empresa** VSAT-ID Link kbps Plataforma **EMC** Brasil 256/128 **VSAT** VIVO-PER- 22011226-PI



Satellite (DVB) RX Configuration

: Enabled

Auto start

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable

* 0 0 25.333333 12.050000 DVB-S2 102 0 0.0 E Yes 1 1 15.000000 12.059000 DVB-S2 4 0 0.0 E Yes 30.000000 12.050000 DVB-S2 102 0 0.0 E Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up Network : 1326, T14R Beam Frequency : 12.049800 GHz : 25.333296 Msps Symbol Rate

S2 ModCod

- receiving : 13 8PSK-2/3 - current max : 20 16APSK-4/5

Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type: MPEG-TS

Roll off : 0.20 SNR : 14.7 dB Input Power : -27 dBm

Satellite (DVB) TX Configuration

Auto start : Enabled IDU Output Power : -22 dBm IDU Max Output Power: 0.0 dBm ODU Output Power : 33.7 dBm

EIRP : 47.0 dBW

Default CW Frequency: 14.125850 GHz

ATM mode : VC-Mux Header Compression : None

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2) IDU Output Power : -14.3 dBm ODU Output Power : 32.0 dBm

EIRP : 45.3 dBW Es/No : 12.0 dB

Header Compression: Disabled Timing correction: -81 us (248729 us)

Frequency correction: -40 Hz

```
Administrator Prompt de Comando

Hicrosoft Windows (versão 6.1.7681)

Copyright (c) 2009 Microsoft Corporation. Todos os direitos reservados.

C:\Users\Asus\ping 8.8.8.8 -t

Disparando 8.8.8.8 con 32 bytes de dados:

Resposta de 8.8.8.8: bytes-32 tenpo=644ns TIL=44

Resposta de 8.8.8.8: bytes-32 tenpo=197ns TIL=44

Resposta de 8.8.8.8: bytes-32 tenpo=186ins TIL=44

Resposta de 8.8.8.8: bytes-32 tenpo=726ins TIL=44

Resposta de 8.8.8.8: bytes-32 tenpo=196ins TIL
```