TERMO DE ACEITE TÉCNICO

Solicitante: VIVO- Projeto Escolas Rurais

**NOC/Operador:** Guilherme Henrique

Cliente: VIVO

Empresa	VSAT-ID	Link kbps	Plataforma
EMC Brasil	VIVO-PER-31193640-MG	256k/128k	VSAT


```
# dvb tx show

Satellite (DVB) TX Configuration
--------------------------------
Auto start          : Enabled
IDU Output Power    : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power    : 33.0 dBm
EIRP                : 46.3 dBW
Default CW Frequency: 14.125750 GHz
ATM mode            : VC-Mux
Header Compression  :  None


Satellite (DVB) Transmitter Status
--------------------------------
State               : On  (DVB-RCS2)
IDU Output Power    : -16.0 dBm
ODU Output Power    : 32.4 dBm
```

```
EIRP                 : 45.7 dBW
Es/No                : 13.0 dB
Header Compression   : Disabled
Timing correction    : -67 us (255438 us)
Frequency correction: 40 Hz
# dvb rx show


Satellite (DVB) RX Configuration
--------------------------------
Auto start           : Enabled
Max Traffic MODCOD   : 23   16APSK-9/10
RX watchdog          : 15 minute

Idx  Pri  SymbRate[Msps] Freq[GHz] Mode   PopId   SatId  Pos   SatName          Name
Enable
* 0  0     15.000000      12.059000 DVB-S2 102        0   0.0 E
Yes
  1  1      9.320000      12.055825 DVB-S2 4          0   0.0 E
Yes


Satellite (DVB) Receiver Status
--------------------------------
Rx State             : On
DVB State            : Forward link up
Network              : 1326,  T14R Beam
Frequency            : 12.059022 GHz
Symbol Rate          : 14.999971 Msps
S2 ModCod
      - receiving    : 14   8PSK-3/4
      - current max  : 20   16APSK-4/5
Pilot                : On
Frame length         : Short
DVB S2 Mode          : ACM
DVB S2 Stream type   : MPEG-TS
Roll off             : 0.20
SNR                  : 14.3 dB
Input Power          : -26 dBm
```

SatLink VSAT   Gmail   +

10.29.41.41/wmi/dwp/index_page.dwp

Mais visitados   Primeiros passos   WhatsApp   Galeria do Web Slice   Sites Sugeridos   PGMEI - Pr

STM

SatLink VSAT

Status
Satellite
Statistics
Device
DHCP
Eventlog
Configuration
Satellite
IP
Static NAT
Lineup
Device
Help
Introduction
Status
Configuration

Device Status

Model	SatLink 2000
Software Version	16.0.1.57
LAN MAC Address	00:20:0e:10:4c:22
DVB MAC Address	00:20:0e:10:4c:22
System Up Time	0 days, 00:39:06
CPU Load	20%
System Name	VIVO-PER-31193640-MG
System Contact	
System Location	LAFAIETE - MG
ODU Serial Number	10480404020309021317000
ODU HW Version	4.2

You are logged in as install (2

© Copyright 2006-2014 STM Group. All R

Prompt de comando

```
Resposta de 8.8.8.8: bytes=32 tempo=1285ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=746ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=783ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=867ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=2012ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=247ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=819ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=907ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=635ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=688ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=770ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=858ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=1997ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=717ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=794ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=523ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=952ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=1772ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=1066ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=1433ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=1441ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=727ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=797ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=520ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=594ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=687ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=1699ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=842ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=927ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=1001ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=1076ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=1799ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=1075ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=1841ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=1752ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=699ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=796ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=855ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=938ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=658ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=857ms TTL=55
Resposta de 8.8.8.8: bytes=32 tempo=941ms TTL=55

Estatísticas do Ping para 8.8.8.8:
    Pacotes: Enviados = 194, Recebidos = 194, Perdidos = 0 (0% de perda),
Aproximar um número redondo de vezes em milissegundos:
    Mínimo = 514ms, Máximo = 2702ms, Média = 900ms
Control-C
^C
C:\Documents and Settings\Administrador>
```

segunda-feira, 5 de junho de 2017

Iniciar   SatLink VSAT - Mozilla Fir...   Telnet 10.29.41.41   **Prompt de comando**   tx rx - Paint   10:08