


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Wallace Teixeira Operadora/Cliente: Eduardo Tadra

GRE/Prodemge: João Antinossi Responsável/cliente: Maria angela de andrade costa

> Plataforma Consórcio **VSAT-ID** Porta kbps EMC/Vodanet SEE-GOES-22798 2MBPS **VSAT**



dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10

: 15 minute RX watchdog

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 0 0.0 E * 0 0

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status _____

Rx State : On

DVB State

: Forward link up : 65281, Prodemge@Vodanet Network

Frequency : 12.176432 GHz Symbol Rate : 4.882916 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6 - current max : 21

: On Pilot Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS

```
Roll off
                    : 0.20
SNR
                    : 15.5 dB
Input Power
                    : -35 dBm
# dvb tx show
Satellite (DVB) TX Configuration
-----
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
                    : 46.5 dBW
EIRP
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -17.6 dBm
ODU Output Power : 33.3 dBm
EIRP
                    : 46.6 dBW
Es/No
                    : 8.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -183 us (281246 us)
Frequency correction: -60 Hz
# device show
System Information:
            : SEE-GOES-22798
   Name
    Location
                        : GOVERNADOR VALADARES
    Contact
                        :
    System Up time : 0 days, 04:50:15

CPU Load : 8%

System time(UTC) : 17 November 2017 05:19:05
    Broadcast Message : not set
HW:
                        : SatLink 2000
    Model
    HW ID
                        : 120033
    Main board ID
                       : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:4f:7b
Satellite (DVB) : 00:20:0e:10:4f:7b
# arp show
   NetAddr State MacAddr
   10.214.212.2 Dynamic ec:a8:6b:ef:7b:f8 1
Pinging 10.214.212.1 with 32 bytes of data:
Reply from 10.214.212.1: bytes=32 time=595ms TTL=56
Reply from 10.214.212.1: bytes=32 time=548ms TTL=56
Reply from 10.214.212.1: bytes=32 time=573ms TTL=56
Reply from 10.214.212.1: bytes=32 time=576ms TTL=56
Reply from 10.214.212.1: bytes=32 time=578ms TTL=56
Reply from 10.214.212.1: bytes=32 time=571ms TTL=56
Reply from 10.214.212.1: bytes=32 time=558ms TTL=56
Reply from 10.214.212.1: bytes=32 time=558ms TTL=56
Reply from 10.214.212.1: bytes=32 time=562ms TTL=56
Reply from 10.214.212.1: bytes=32 time=571ms TTL=56
Ping statistics for 10.214.212.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
```

Approximate round trip times in milli-seconds: Minimum = 548ms, Maximum = 595ms, Average = 569ms
Lista de sites acessados:
www.globo.com – ok
www.yahoo.com – ok
www.hotmail.com – ok
www.google.com – ok
www.educacao.mg.gov.br – ok
<u>www.prodemge.gov.br</u> – ok
Responsável pelo teste de navegação:
Nome: Maria angela de andrade costa
Função: Diretora
Identidade: MASP: 991602-4