

TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE


NOC/Operadora: Gustavo Henrique Operadora/Cliente: Ederson Martins

Responsável/cliente: SARA LUCIANA SOARES GRE/Prodemge: João Antinossi

GUIMARÃES

Consórcio **VSAT-ID** Porta kbps **Plataforma** EMC/Vodanet **VSAT SEE-PAHO-23825** 2Mbps

Port eth0 on SEE-PAHO-23825 10.214.5.1



dvb rx show

Satellite (DVB) RX Configuration Auto start : Enabled

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

13.333333 * 0 0 12.173500 DVB-S2 104 0 0.0 E Yes

1 8.883000 12.176420 DVB-S2 2 0 0.0 E 1

Yes

Satellite (DVB) Receiver Status _____

Rx State : On

DVB State : Forward link up

: 65281, Prodemge@Vodanet Network

Frequency : 12.173504 GHz Symbol Rate : 13.332978 Msps

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

: On Pilot : Short Frame length DVB S2 Mode : ACM

```
DVB S2 Stream type : MPEG-TS
Roll off : 0.20
SNR : 14.7 dB
Input Power
                    : -40 dBm
# dvb tx show
Satellite (DVB) TX Configuration
-----
Auto start
                    : Enabled
Auto start : Enabled IDU Output Power : -18 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
ATM mode
                    : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
: On (DVB-RCS2)

IDU Output Power : -17.9 dBm

Es/No

Headar 5
_____
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -429 us (259409 us)
Frequency correction: 90 Hz
# device show
System Information:
                        : SEE-PAHO-23825
   Name
    Location
                        : Padre Carvalho - MG
    Contact
   System Up time : 0 days, 00:20:26 CPU Load : 32%
    System time(UTC) : 30 January 2018 13:10:26
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:93:96
Satellite (DVB) : 00:20:0e:10:93:96
   Ethernet (LAN)
# arp show
                State MacAddr
     10.214.5.2 Dynamic 1c:39:47:5b:e2:48 1
#
C:\Documents and Settings\Administrator.DVB-RCS.000>ping 10.214.5.1 -n 10
Pinging 10.214.5.1 with 32 bytes of data:
Reply from 10.214.5.1: bytes=32 time=538ms TTL=56
Reply from 10.214.5.1: bytes=32 time=545ms TTL=56
Reply from 10.214.5.1: bytes=32 time=724ms TTL=56
Reply from 10.214.5.1: bytes=32 time=542ms TTL=56
Reply from 10.214.5.1: bytes=32 time=531ms TTL=56
Reply from 10.214.5.1: bytes=32 time=539ms TTL=56
Reply from 10.214.5.1: bytes=32 time=553ms TTL=56
Reply from 10.214.5.1: bytes=32 time=557ms TTL=56
```

```
Reply from 10.214.5.1: bytes=32 time=550ms TTL=56
Reply from 10.214.5.1: bytes=32 time=562ms TTL=56

Ping statistics for 10.214.5.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 531ms, Maximum = 724ms, Average = 564ms
```

Lista de sites acessados:

www.globo.com - ok www.yahoo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok

Responsável pelo teste de navegação:

Nome: SARA LUCIANA SOARES GUIMARÃES

Função: Diretora MASP: 113.3893-6