


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior Operadora/Cliente: Fabio Fernandes

GRE/Prodemge: João Antinossi Responsável/cliente: Glaucia Maria Campos Figueiredo

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-SERO-220522MbpsVSAT



PRTG Traffic Grapher V6.2.0.907 - 12/10/2017 17:14:27

dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E Yes 1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176408 GHz Symbol Rate : 4.882940 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 16 8PSK-8/9

Pilot : On

Frame length : Short DVB S2 Mode : ACM

DVB S2 Stream type: MPEG-TS

Roll off : 0.20 SNR : 16.3 dB Input Power : -30 dBm

Satellite (DVB) TX Configuration

Auto start : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm

EIRP : 46.5 dBW

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2)
IDU Output Power : -16.3 dBm
ODU Output Power : 33.1 dBm

EIRP : 46.4 dBW Es/No : 14.0 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction : -362 us (281636 us)

Frequency correction: 80 Hz

device show

System Information:

Name : SEE-SERO-22052

Location : SERRO

Contact

System Up time : 0 days, 00:09:52

CPU Load : 9%

System time(UTC) : 12 October 2017 15:41:20

Broadcast Message : not set

HW:

Model : SatLink 2000 HW ID : 120033

Main board ID : 120026 R6.2

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:4a:ae Satellite (DVB) : 00:20:0e:10:4a:ae

arp show

NetAddr State MacAddr If

10.212.124.2 Dynamic 00:40:a7:18:42:6e 1

Pinging 10.212.124.1 with 32 bytes of data:

Reply from 10.212.124.1: bytes=32 time=566ms TTL=56 Reply from 10.212.124.1: bytes=32 time=623ms TTL=56 Reply from 10.212.124.1: bytes=32 time=578ms TTL=56 Reply from 10.212.124.1: bytes=32 time=596ms TTL=56 Reply from 10.212.124.1: bytes=32 time=572ms TTL=56 Reply from 10.212.124.1: bytes=32 time=574ms TTL=56 Reply from 10.212.124.1: bytes=32 time=574ms TTL=56 Reply from 10.212.124.1: bytes=32 time=589ms TTL=56 Reply from 10.212.124.1: bytes=32 time=597ms TTL=56 Reply from 10.212.124.1: bytes=32 time=572ms TTL=56 Reply from 10.212.124.1: bytes=32 time=572ms TTL=56 Reply from 10.212.124.1: bytes=32 time=614ms TTL=56

Ping statistics for 10.212.124.1:

Packets: Sent = 11, Received = 11, Lost = 0 (0% loss), Approximate round trip times in milli-seconds: Minimum = 555ms, Maximum = 623ms, Average = 585ms

Lista de sites acessados:

www.globo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br- ok

Responsável pelo teste de navegação:

Nome: Glaucia Maria Campos Figueiredo

Função: Diretora

Identidade: 951728-5(MASP)