


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Joao Carlos

GRE/Prodemge: João Antinossi Responsável/cliente: Juliana Barcelos Calcado

> Porta kbps Plataforma Consórcio **VSAT-ID** EMC/Vodanet **VSAT** SEE-COES-22825 2Mbps



Satellite (DVB) RX Configuration _____

Auto start : Enabled

: 23 16APSK-9/10 Max Traffic MODCOD

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

: On Rx State

DVB State : Forward link up

: 65281, Prodemge@Vodanet Network

: 12.176260 GHz : 4.883051 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length DVB S2 Mode : Short : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.9 dB Input Power : -39 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.5 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
______
State : On (DVB-RCS2)
IDU Output Power : -10.5 dBm
ODU Output Power : 33.8 dBm
EIRP
                    : 46.8 dBW
Es/No
                    : 14.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -31 us (283911 us)
Frequency correction: 90 Hz
System Information:
    Name
                       : SEE-COES-22825
    Location
                        : Comendador Gomes-MG
    Contact
    System Up time : 0 days, 01:49:57 CPU Load : 14%
    System time(UTC) : 20 November 2017 15:27:17
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                       : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:57:47
Satellite (DVB) : 00:20:0e:10:57:47
    Ethernet (LAN)
NetAddr
          State MacAddr
   10.215.195.2 Dynamic 54:04:a6:8e:d3:f6 1
Pinging 10.215.195.1 with 32 bytes of data:
Reply from 10.215.195.1: bytes=32 time=636ms TTL=56
Reply from 10.215.195.1: bytes=32 time=529ms TTL=56
Reply from 10.215.195.1: bytes=32 time=610ms TTL=56
Reply from 10.215.195.1: bytes=32 time=692ms TTL=56
Reply from 10.215.195.1: bytes=32 time=533ms TTL=56
Reply from 10.215.195.1: bytes=32 time=618ms TTL=56
Reply from 10.215.195.1: bytes=32 time=580ms TTL=56
Reply from 10.215.195.1: bytes=32 time=615ms TTL=56
Reply from 10.215.195.1: bytes=32 time=553ms TTL=56
Reply from 10.215.195.1: bytes=32 time=609ms TTL=56
Ping statistics for 10.215.195.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 529ms, Maximum = 692ms, Average = 597ms
```

Tieto de sites assessados:
Lista de sites acessados: www.globo.com – ok
<u>www.yahoo.com</u> – ok <u>www.yahoo.com</u> – ok
www.hotmail.com – ok
www.google.com – ok
www.educacao.mg.gov.br – ok
www.prodemge.gov.br – ok
Responsável pelo teste de navegação:
Nome: Juliana Barcelos Calcado
Função: Secretária
MASP: 1230566.0
Telefone: 34-3423-1212
Funcionamento: 07:00h às 13:00h e 16:30h às 22:15h