

TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior


Operadora/Cliente João Sobrinho

GRE/Prodemge: João Antinossi

Responsável/cliente José Heleno Cardoso

Consórcio
EMC/Vodanet

VSAT-ID
SEE-MOUL-22537
SEE-MOUL-22537
VSAT



SatLink 2000

- Main board ID 120026, Revision R6.2

- SW ID 120208, Revision 16.0.1 Build 57

dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E Yes 1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176291 GHz Symbol Rate : 4.882952 Msps

S2 ModCod

- receiving : 19 16APSK-3/4 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short
DVB S2 Mode : ACM
DVB S2 Stream type : MPEG-TS

Roll off : 0.20 SNR : 16.2 dB Input Power : -26 dBm

dvb tx show

```
Satellite (DVB) TX Configuration
Auto start
             : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : max
EIRP
             : max
Default CW Frequency: 0.000000 GHz
ATM mode
                : VC-Mux
Header Compression: UDP/IP
Satellite (DVB) Transmitter Status
            : On (DVB-RCS2)
IDU Output Power : -18.6 dBm
ODU Output Power : 34.1 dBm
EIRP
             : 47.4 dBW
Es/No
             : 14.5 dB
Header Compression: Disabled - HC for RCS2 not supported by HUB
Timing correction: -383 us (280788 us)
Frequency correction: 120 Hz
# arp show
 NetAddr
             State MacAddr
 10.213.120.2 Dynamic b4:99:ba:00:92:6b 1
# device show
System Information:
                : SEE-MOUL-22537
  Name
                : Monte Azul - MG
  Location
  Contact
  System Up time
                  : 0 days, 00:07:10
                 : 15%
  CPU Load
  System time(UTC) : 06 November 2017 15:25:16
  Broadcast Message : not set
HW:
                : SatLink 2000
  Model
                : 120033
  HW ID
  Main board ID
                  : 120026 R6.2
MAC addresses:
  Ethernet (LAN)
                   : 00:20:0e:10:5b:f2
  Satellite (DVB) : 00:20:0e:10:5b:f2
Pinging 10.213.120.1 with 32 bytes of data:
Reply from 10.213.120.1: bytes=32 time=547ms TTL=56
Reply from 10.213.120.1: bytes=32 time=526ms TTL=56
Reply from 10.213.120.1: bytes=32 time=587ms TTL=56
Reply from 10.213.120.1: bytes=32 time=507ms TTL=56
Reply from 10.213.120.1: bytes=32 time=550ms TTL=56
Reply from 10.213.120.1: bytes=32 time=558ms TTL=56
Reply from 10.213.120.1: bytes=32 time=514ms TTL=56
Reply from 10.213.120.1: bytes=32 time=590ms TTL=56
Reply from 10.213.120.1: bytes=32 time=513ms TTL=56
Reply from 10.213.120.1: bytes=32 time=529ms TTL=56
Ping statistics for 10.213.120.1:
  Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
  Minimum = 513ms, Maximum = 590ms, Average = 542ms
```

www.globo.com

www.yahoo.com.br

www.hotmail.com www.google.com

www.prodemge.gov.br

Responsável	José Heleno Cardoso
Cargo	Diretor
Identidade	859749-4
Telefone	038-9-9839-8126
Funcionamento	07:00 às 17:00