

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: João Gustavo

GRE/Prodemge: João Antinossi Responsável/cliente: José Delio Vieira

> Porta kbps Plataforma Consórcio **VSAT-ID** EMC/Vodanet SEE-INRA-22779 2Mbps VSAT





Satellite (DVB) RX Configuration -----

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

12.176420 DVB-S2 104 0 0.0 E * 0 0 4.883300

Yes

16.667000 11.962753 DVB-S2 2 0 0.0 E 1 1

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

: 00201, -: 12.175428 GHz : 4.883055 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.0 dB Input Power : -36 dBm

```
Satellite (DVB) TX Configuration
 _____
Auto start
                                           : Enabled
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : max
EIRP
                                            : max
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
: On (DVB-RCS2)

IDU Output Power : -16.0 dBm

ODU Output Power : 34.8 dBm

EIRP
______
Es/No
                                            : 15.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -341 us (280477 us)
Frequency correction: 60 Hz
System Information:
                                           : SEE-INRA-22779
        Name
         Location
                                                     : Indaiabira - MG
         Contact
        System Up time : 0 days, 00:16:44 CPU Load : 13%
        System time (UTC) : 14 November 2017 14:21:43
         Broadcast Message : not set
HW:
        Model
                                                    : SatLink 2000
         HW ID
                                                    : 120033
         Main board ID
                                                   : 120026 R6.2
        converse convence converse converse converse converse converse converse convers
MAC addresses:
NetAddr
                        State MacAddr
         10.214.87.2 Dynamic b4:99:ba:00:92:6b 1
Pinging 10.214.87.1 with 32 bytes of data:
Reply from 10.214.87.1: bytes=32 time=547ms TTL=56
Reply from 10.214.87.1: bytes=32 time=553ms TTL=56
Reply from 10.214.87.1: bytes=32 time=516ms TTL=56
Reply from 10.214.87.1: bytes=32 time=594ms TTL=56
Reply from 10.214.87.1: bytes=32 time=550ms TTL=56
Reply from 10.214.87.1: bytes=32 time=596ms TTL=56
Reply from 10.214.87.1: bytes=32 time=544ms TTL=56
Reply from 10.214.87.1: bytes=32 time=570ms TTL=56
Reply from 10.214.87.1: bytes=32 time=540ms TTL=56
Reply from 10.214.87.1: bytes=32 time=552ms TTL=56
Ping statistics for 10.214.87.1:
         Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
         Minimum = 516ms, Maximum = 596ms, Average = 556ms
```

Lista de sites acessados: <u>www.globo.com</u> – ok www.yahoo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br – ok www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: José Delio Vieira Função: Diretor MASP: 594754-4 Telefone: 38-99735-4652 Funcionamento: 07:00 às 22:10h