

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Paulo de Tarso Operadora/Cliente: Gilvan P de Brito Júnior

Responsável/cliente: : João de Deus Ferreira dos GRE/Prodemge: João Antinossi

Anjos

Consórcio VSAT-ID Porta kbps **Plataforma** EMC/Vodanet SEE-SACO-22220 2048/1024 VSAT



Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 0 0.0 E * 0 0

Yes

Satellite (DVB) Receiver Status _____

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176312 GHz : 4.882956 Msps Symbol Rate

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On Pilot : On
Frame length : Shor
DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.6 dB Input Power : -32 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -21 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
: On (DVB-RCS2)

IDU Output Power : -16.7 dBm

ODU Output Power : 33.1 dBm

EIRP
_____
Es/No
                     : 14.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -338 us (281771 us)
Frequency correction: 170 Hz
device show
System Information:
              : SEE-SACO-22220
    Name
    Location
                         : S¦O FRANCISCO
    Contact
    System Up time : 0 days, 01:43:53
CPU Load : 21%
System time(UTC) : 03 November 2017 17:19:58
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.1
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:48:49
Satellite (DVB) : 00:20:0e:10:48:49
Reply from 10.213.19.1: bytes=32 time=544ms TTL=56
Reply from 10.213.19.1: bytes=32 time=530ms TTL=56
Reply from 10.213.19.1: bytes=32 time=704ms TTL=56
Reply from 10.213.19.1: bytes=32 time=565ms TTL=56
Reply from 10.213.19.1: bytes=32 time=537ms TTL=56
Reply from 10.213.19.1: bytes=32 time=542ms TTL=56
Reply from 10.213.19.1: bytes=32 time=561ms TTL=56
Reply from 10.213.19.1: bytes=32 time=526ms TTL=56
Reply from 10.213.19.1: bytes=32 time=530ms TTL=56
Reply from 10.213.19.1: bytes=32 time=542ms TTL=56
Ping statistics for 10.213.19.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 526ms, Maximum = 704ms, Average = 558ms
         State MacAddr
NetAddr
                                          Ιf
    10.213.19.2 Dynamic 1c:39:47:5b:e2:48 1
```

Lista de sites acessados: www.globo.com – ok
www.yahoo.com – ok
www.hotmail.com – ok
www.google.com – ok
www.educacao.mg.gov.br – ok
www.prodemge.gov.br – ok
Responsável pelo teste de navegação:
Nome: JOÃO DE DEUS FERREIRA DOS ANJOS
Tel - 038-99835-7722
Função: DIRETOR
MASP: 815721-6
HORÁRIO DAS 07 AS 11:30 hrs